

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012511/GQCN2**Date:** 25/04/2022**REFERENCE**

Insured/Claimant:	GAN CHEONG TECK	Policy No:	2070032301	
Date of Loss:	23/10/2021	Nature of Claim:	OD	Claim No: 5221720747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7456T		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK087991
Reg. Date:	12/03/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF47KA117936
Colour:	Black	Odometer:	24470 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$178,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,808.00	3,033.12	3,774.88	55.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	1,602.00	2,350.00	59.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,760.00	4,635.12	6,124.88	56.92
+ GST 7.00/7.00% (\$\$)	753.20	324.46	428.74	56.92
Nett Amount (\$\$)	11,513.20	4,959.58	6,553.62	56.92

INSPECTION

Date of Assignment:	10/12/2021		
Date Inspected:	09/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,996.00 FS	*2,396.80 FS
2	1		*REAR BUMPER FIXING SET	Not Necessary	459.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	223.00 FS	*178.00 FS
4	1		*REAR BUMPER SPOILER	Deformed	249.00 FS	*198.80 FS
5	1		*REAR BUMPER TRIM	Cut	292.00 FS	*233.20 FS
6	2		*REAR BUMPER BRACKET-LH/RH	Not Necessary	232.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	82.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	1,063.00 FS	*- FS
9	2		*REAR BUMPER SEAL	Not Necessary	28.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	46.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP-LH/RH	Not Necessary	166.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			NPA			
13	4		*REAR PARKING AID SENSOR SEAL	Necessary	14.00 FS	*8.64 FS
14	2		*REAR EXHAUST TRIM-LH/RH	Not Necessary	708.00 FS	*- FS
15	1		*SUNDRIES	Necessary	250.00 FS	*17.68 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					6,808.00	3,033.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			3,952.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >