

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21012512/KVF3N2**Date:** 04/01/2022**REFERENCE**

Insured/Claimant: Chai Chian Wee Policy No: MPC21B00013100
Date of Loss: 06/12/2021 Nature of Claim: OD Claim No: DMPC2100426H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH8008B**
Make & Model: LEXUS IS250, 2.5 (A) Engine No: 4GR0231900
Reg. Date: 25/08/2006 (Man. Year: 2006) Chassis No: JTHBK262102021742
Colour: Metallic Black Odometer: 229950 km
Engine Capacity: 2500 cc
Market Value/New Car Price: S\$47,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,972.15	1,635.90	2,336.25	58.82
Miscellaneous Items	80.00	30.00	50.00	62.50
Labour	1,860.00	960.00	900.00	48.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,912.15	2,625.90	3,286.25	55.58
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	5,912.15	1,875.90	4,036.25	68.27
+ GST 7.00/7.00% (S\$)	413.85	131.31	282.54	68.27
Nett Amount (S\$)	6,326.00	2,007.21	4,318.79	68.27

INSPECTION

Date of Assignment: 09/12/2021

Date Inspected: 10/12/2021 Inspected At:

Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto
Point
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2022)
Parts:	143	LEXUS IS250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH8008B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Repair	800.00 F	*- F
2	1		*FRONT BUMPER (WCP)	Bent	280.00 F	*280.00 F
3	1		*FRONT BUMPERT SIDE RETAINER LH & RH (WCP)	O/s Cracked	80.00 F	*40.00 F
4	1		*FRONT BUMPER TOP RUBBER (WCP)	Necessary	38.00 F	*38.00 F
5	1		*FRONT GRILLE (WCP)	Serviceable	130.00 F	*- F
6	1		*FRONT GRILLE EMBLEM (WCP)	Not Necessary	40.00 F	*- F
7	1		*FRONT NUMBER PLATE GARNISH (WCP)	Serviceable	50.00 F	*- F
8	1		*FRONT BUMPER LOWER GRILLE (WCP)	Serviceable	45.00 F	*- F
9	1		*FRONT RH FOGLAMP (WCP)	Mtg Broken	155.00 F	*155.00 F
10	1		*FRONT RH FOGLAMP SIDE COVER (WCP)	Serviceable	80.00 F	*- F
11	1		*FRONT RH HEADLAMP (WCP)	Mtg Broken	400.00 F	*400.00 F
12	1		*FRONT RH HEADLAMP TOP BRACKET (WCP)	Cracked	90.00 F	*90.00 F
13	1		*FRONT RH HEADLAMP LOWER BRACKET (WCP)	Cracked	60.00 F	*60.00 F
14	1		*FRONT RH FENDER SHIELD (WCP)	Cracked	175.00 F	*175.00 F
15	1		*FRONT RH FENDER (WCP)	Buckled	320.00 F	*320.00 F
16	1		*FRONT REINFORCEMENT BAR (WCP)	Repair	210.00 F	*- F
17	1		*FRONT RH REINFORCEMENT ARM (WCP)	Repair	130.00 F	*- F
18	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	55.00 F	*- F
19	1		*FRONT RADIATOR TOP GARNISH (WCP)	Serviceable	165.00 F	*- F
20	1		*FRONT SUPPORT PANEL (WCP)	Repair	480.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	3,783.00	1,558.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	189.15	77.90
Total Parts (\$\$)	3,972.15	1,635.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER & RADIATOR TOP GARNISH CLIPS (Not Necessary)	50.00	0.00
2	1	FRONT FENDER SHIELD CLIPS (Necessary)	30.00	30.00
Sub Total (\$\$)			80.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	800.00	540.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	400.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	80.00	20.00
4	TO REMOVE/REFIX RADIATOR & AIRCON CONDENSOR FOR REPLACE SUPPORT PANEL (TOP UP AIRCON GAS, RADIATOR & ETC..)	New	180.00	0.00
Gross Labour Cost (\$\$)			1,860.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >