

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI21012518/KVCN2**Date:** 22/12/2021**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000071
<b>Claimant Vehicle No :</b>	SHD9070Y	<b>Insured Vehicle No :</b>	SLP1948H
Date of Loss:	01/12/2021	Nature of Claim:	TP
		Claim No:	M2105751

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD9070Y</b>	Engine No:	2ZR2B68398
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU903076118
Reg. Date:	01/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 5 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,149.85	3,341.00	3,808.85	53.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	2,020.00	2,770.00	57.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,939.85</b>	<b>5,361.00</b>	<b>6,578.85</b>	<b>55.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>(S\$)</b>	11,939.85	4,300.00	7,639.85	63.99
<b>+ GST 7.00/7.00% (S\$)</b>	835.79	301.00	534.79	63.99
<b>Nett Amount (S\$)</b>	<b>12,775.64</b>	<b>4,601.00</b>	<b>8,174.64</b>	<b>63.99</b>

**INSPECTION**

Date of Assignment:	13/12/2021	
Date Inspected:	09/12/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	6.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2021)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9070Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*PANEL SUB-ASSY,FRONT DOOR RH	Repair	1,300.70 FL	-	*- FL
2	1		*FRAME SUB-ASSY,FRONT DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	-	*- FL
3	1		*HANDLE ASSY,FRONT DOOR,OUTSIDE RH	Serviceable	390.60 FL	-	*- FL
4	1		*HINGE ASSY,FRONT DOOR,LOWER RH	Repair	110.60 FL	-	*- FL
5	1		*HINGE ASSY,FRONT DOOR,UPPER RH	Repair	97.50 FL	-	*- FL
6	1		*TAPE BLACK OUT,NO 1 FRT RH	Not Necessary	13.30 FL	-	*- FL
7	1		*TAPE BLACK OUT,NO 2 FRT RH	Not Necessary	43.50 FL	-	*- FL
8	1		*TAPE BLACK OUT,NO 3 FRT RH	Not Necessary	26.30 FL	-	*- FL
9	1		*MOTOR ASSY,POWER WINDOW REGULATOR,FRT RH	Serviceable	926.00 FL	-	*- FL
10	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,RH	Serviceable	238.30 FL	-	*- FL
11	1		*WEATHERSTRIP,FRONT DOOR,RH	Serviceable	231.30 FL	-	*- FL
12	1		*PANEL SUB-ASSY,REAR DOOR,RH	Bent	1,294.90 FL	-	*1,294.90 FL
13	1		*HANDLE ASSY,REAR DOOR,OUTSIDE RH	Serviceable	97.40 FL	-	*- FL
14	1		*FRAME SUB-ASSY,REAR DOOR OUTSIDE HANDLE,RH	Serviceable	193.50 FL	-	*- FL
15	1		*HINGE ASSY,REAR DOOR,LOWER RH	Repair	87.10 FL	-	*- FL
16	1		*HINGE ASSY,REAR DOOR,UPPER RH	Repair	98.90 FL	-	*- FL
17	1		*TAPE BLACK OUT,NO 1 REAR RH	Necessary	21.90 FL	-	*21.90 FL
18	1		*TAPE BLACK OUT,NO 2 REAR RH	Necessary	34.90 FL	-	*34.90 FL
19	1		*TAPE BLACK OUT,NO 3 REAR RH	Necessary	15.40 FL	-	*15.40 FL
20	1		*MOTOR ASSY,POWER WINDOW REGULATOR,REAR RH	Jammed	926.00 FL	-	*926.00 FL
21	1		*REGULATOR SUB-ASSY,REAR DOOR WINDOW,RH	Bent	206.70 FL	-	*206.70 FL
22	1		*WEATHERSTRIP,REAR DOOR,RH	Serviceable	180.10 FL	-	*- FL
23	1		*PANEL SUB-ASSY,QUARTER,RH	Bent	871.50 FL	-	*871.50 FL
24	1		*LINER,REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	-	*- FL
25	1		*MOULDING ASSY,BODY ROCKER PANEL,RH	Buckled	594.80 FL	-	*594.80 FL
26	1		*REINFORCEMENT SUB-ASSY,ROCKER PANEL,RH	Repair	343.40 FL	-	*- FL
27	1		*CLIP (FOR FRONT DOOR TRIM BOARD)	Not Necessary	65.00 FS	-	*- FS
28	1		*CLIP (FOR REAR DOOR TRIM BOARD)	Not Necessary	65.00 FS	-	*- FS
29	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	-	*60.00 FS
30	1		*FRT DOOR STICKER TRANSCAB	Necessary	100.00 FS	-	*60.00 FS
31	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	-	*- FS
32	1		*ROCKER PANEL CLIP	Necessary	65.00 FS	-	*65.00 FS
33	1		*COVER,FLOOR UNDER NO 2 (RH)	Distorted/Cracked	241.90 FL	-	*241.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,379.80</b>	<b>4,393.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,229.95</b>	<b>1,052.00</b>
<b>Total Parts (\$\$)</b>	<b>7,149.85</b>	<b>3,341.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	880.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	100.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,800.00	900.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>4,790.00</b>	<b>2,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >