

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012526/UTY3N2**Date:** 07/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00005422101

Claimant Vehicle No : GBG8802P **Insured Vehicle No :** SMQ6255Z

Date of Loss: 03/12/2021 Nature of Claim: TP Claim No: SNM21D207105/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG8802P**

Make & Model: TOYOTA DYNA 300, 3.0 D (M) Engine No: 1KD2747829

Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: KDY2318031501

Colour: Silver Odometer: 119722 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 155R13 (D)

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6/6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,193.00	2,054.27	3,138.73	60.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	910.00	870.00	48.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,973.00	2,964.27	4,008.73	57.49
Approved Total (Overridden) (\$\$)		2,350.00		
(\$\$)	6,973.00	2,350.00	4,623.00	66.30
+ GST 7.00/7.00% (\$\$)	488.11	164.50	323.61	66.30
Nett Amount (\$\$)	7,461.11	2,514.50	4,946.61	66.30

INSPECTION

Date of Assignment: 07/02/2022

Date Inspected: 21/01/2022 Inspected At: Auto Bay@ Kaki Bukit
Avenue 6 Entrance A #01-04
Repairer: KT Garage Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Mar 2022)	
Parts:	N/A	TOYOTA DYNA 300 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8802P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	681.10 FL	*681.10 FL
2	1		*FRONT BUMPER BRACKET-LH	Not Necessary	683.00 FL	*- FL
3	1		*HEADLAMP-LH	Cracked	455.00 FL	*455.00 FL
4	1		*HEADLAMP LOWER RUBBER SEAL-LH	Not Necessary	35.00 FL	*- FL
5	1		*LH FRONT CORNER PANEL	Repair	560.00 FL	*- FL
6	1		*LH FRONT CORNER PANEL CLIPS	Not Necessary	92.50 FL	*- FL
7	1		*LH FRONT DOOR	Dented	1,261.10 FL	*1,261.10 FL
8	1		*LH FRONT DOOR SIGNAL LAMP	Broken	184.60 FL	*148.50 FL
9	2		*LH FRONT DOOR UNDER SEAL	Not Necessary	16.00 FL	*- FL
10	1		*LH FRONT DOOR INNER TRIM BOARD	Not Necessary	1,033.61 FL	*- FL
11	1		*LH STEP GARNISH	Serviceable	462.54 FL	*- FL
12	1		*COMPANY REGISTRATION STICKER	Necessary	25.00 FS	*25.00 FS
13	1		*COMPANY STICKER	Necessary	250.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,739.45	2,690.70
- List Item Discount on L Items 10.00/25.00% (\$\$)	546.45	636.43
Total Parts (\$\$)	5,193.00	2,054.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN NECESSARY PORTION	New	900.00	300.00
2	TO CHECK ALL NECESSARY LIGHTINGS	New	80.00	20.00
3	TO RUST PROOF THE AFFECTED AREAS	New	80.00	30.00
4	TO SPRAY PAINT THE AFFECTED AREAS	New	600.00	500.00
5	TO TRANSFER DOOR MECHANIC	New	120.00	60.00
Gross Labour Cost (\$)			1,780.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >