

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012527/R1TY3E2

Date: 04/01/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00020252105
Claimant Vehicle No : SBS6443S **Insured Vehicle No :** GBD6864P
Date of Loss: 08/12/2021 Nature of Claim: TP Claim No: SNM21D207127/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6443S**
Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO Engine No: 902926C1029172
Reg. Date: 02/05/2014 (Man. Year: 2013) Chassis No: WEB62808323125358
Colour: Green Odometer: 522378 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Firenza 8 mm Rear Left Side: Firenza 8/8 mm
Front Right Side: Firenza 8 mm Rear Right Side: Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,072.67	4,072.67	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	975.00	1,625.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,672.67	5,047.67	1,625.00	24.35
+ GST 7.00/7.00% (S\$)	467.09	353.34	113.75	24.35
Nett Amount (S\$)	7,139.76	5,401.01	1,738.75	24.35

INSPECTION

Date of Assignment: 10/12/2021
Date Inspected: 13/12/2021 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Jan 2022)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SBS6443S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS ELECTRIC - DRIVERS SIDE	Broken	2,272.01 F	*2,272.01 F
2	1		*OSF MIRROR HEATED ELECTRONICALLY ADJUSTABLE	Distorted	1,728.66 F	*1,728.66 F
3	1		*SIKAFLEX BLACK	Necessary	32.00 F	*32.00 F
4	1		*REFLECTOR STICKER	Necessary	40.00 F	*40.00 F
F=Franchise part.						
					Total Parts (S\$)	4,072.67 4,072.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE :- GLASS ELECTRIC - DRIVERS SIDE - OSF MIRROR HEATED ELECTRONICALLY ADJUSTABLE - SIKAFLEX BLACK - REFLECTOR STICKER	New	2,600.00	975.00
Gross Labour Cost (\$)			2,600.00	975.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >