

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012528/UGA3Q2**Date:** 15/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700084674
Claimant Vehicle No :	SLZ9498J	Insured Vehicle No :	SLU4235K
Date of Loss:	08/12/2021	Nature of Claim:	TP
		Claim No:	5961421060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ9498J	Engine No:	LEB6550177
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71208327
Reg. Date:	23/05/2018 (Man. Year: 2018)	Odometer:	220260 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,533.60	5,263.28	5,270.32	50.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	2,030.00	510.00	20.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,073.60	7,293.28	5,780.32	44.21
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	13,073.60	5,800.00	7,273.60	55.64
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
Nett Liability (S\$)		6,440.00		

INSPECTION

Date of Assignment:	10/12/2021	
Date Inspected:	10/12/2021	Inspected At: Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Badly Dented	1,193.60 F	*1,193.60 FL
2	1		*REAR BOOTLID LOCK	Bent / Shorted	186.90 F	*186.90 FL
3	1		*REAR BOOTLID RUBBER	Twisted	168.50 F	*168.50 FL
4	1		*REAR BOOTLID EMBLEM	Necessary	120.70 F	*55.40 FL
5	1		*REAR BOOTLID H EMBLEM	Necessary	27.40 F	*27.40 FL
6	2		*REAR BOOTLID ABSORBER	Not Necessary	353.40 F	*- FL
7	2		*REAR BOOTLID REFLECTOR LAMP	Not Necessary	681.60 F	*- FL
8	1		*REAR BOOTLID INNER TRIMBOARD	Deformed / Torn	388.90 F	*320.40 FL
9	1		*REAR BOOTLID INNER HANDLE GARNISH	Not Necessary	25.60 F	*- FL
10	1		*REAR BOOTLID CHROME MOULDING & GARNISH	Not Necessary	383.10 F	*- FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	153.80 F	*149.20 FL
12	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS
13	1		*REAR WINDSCREEN INNER SEAL	Necessary	26.00 FS	*26.00 FS
14	2		*REAR TAILLAMP	Cracked	1,021.00 F	*1,021.00 FL
15	4		*REAR TAILLAMP CLIPS	Not Necessary	16.80 F	*- FL
16	1		*REAR FENDER INNER TRIM BOARD	O/S Not Necessary / N/S Torn	911.60 F	*394.10 FL
17	1		*REAR END PANEL	Badly Dented	560.50 F	*560.20 FL
18	1		*REAR END PANEL GARNISH	Twisted	138.60 F	*138.60 FL
19	1		*REAR END PANEL LOCK STRIKER	Not Necessary	37.60 F	*- FL
20	1		*REAR SPARE WHEEL PANEL	Repair	956.40 F	*- FL
21	1		*REAR SPARE WHEEL PANEL COMPARTMENT GARNISH	Twisted	380.60 F	*380.60 FL
22	1		*REAR SPARE WHEEL PANEL COMPARTMENT SPONGE	No such part	265.20 F	*- FL
23	1		*REAR SPARE WHEEL PANEL TOP COVER GARNISH	Warped	327.80 F	*327.80 FL
24	1		*REAR BUMPER	Dented	1,150.60 F	*936.50 FL
25	1		*SET REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
26	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
27	8		*REAR BUMPER CLIPS	Necessary	31.20 F	*31.20 FL
28	2		*REAR BUMPER SIDE RETAINER	Bent	57.20 F	*57.20 FL
29	2		*REAR BUMPER REFLECTOR	Cracked / Twisted	91.60 F	*91.60 FL
30	2		*REAR BUMPER REFLECTOR COVER GARNISH	Twisted	93.60 F	*93.60 FL
31	2		*REAR BUMPER INNER SPONGE	Torn	112.80 F	*112.80 FL
32	1		*REAR NO PLATE	Not Necessary	26.00 FS	*- FS
33	1		*REAR NO PLATE COVER	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,533.60	6,512.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,249.32
Total Parts (\$\$)	10,533.60	5,263.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY PAINTING (PEARL RED)	New	1,200.00	900.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIX REAR INTERIOR UPHOSLY	New	80.00	80.00
5	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	60.00
6	TO MEASURE & DRILL REAR BUMPER ,POSITION & INSTALL REAR REVERSE SENSOR ,REAR CAMERA ,CONTROL UNTIL ,CHECK & TEST FOR FUNCTIONING	New	80.00	50.00
7	TO PANEL BEATING ,WELDING ,REMOVE ALL DAMAGE PARTS & REPLACING OF THE NEW PARTS ETC	New	900.00	800.00
Gross Labour Cost (\$\$)			2,540.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >