

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012533/UPA3Q2**Date:** 29/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0000768_02

Claimant Vehicle No : FBR7473D **Insured Vehicle No :** XE2706Z

Date of Loss: 05/12/2021 Nature of Claim: TP Claim No: MFL2021D0005592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR7473D**

Make & Model: HONDA NC750XA, 745cc Engine No: RC88E5203230

Reg. Date: 12/10/2020 (Man. Year: 2019) Chassis No: JH2RC90A8KK302596

Colour: White Odometer: 80449 km

Engine Capacity: 745 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 160/60Z R17

Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,342.00	7,877.80	5,464.20	40.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,092.00	935.00	1,157.00	55.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,434.00	8,812.80	6,621.20	42.90
+ GST 7.00/7.00% (S\$)	1,080.38	616.90	463.48	42.90
Nett Amount (S\$)	16,514.38	9,429.70	7,084.68	42.90
+ Loss of Use (7.0 x S\$20.00/day) (S\$)		140.00		
(S\$)		9,569.70		
Liabe Amount (80.00%) (S\$)		7,655.76		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,663.21		

INSPECTION

Date of Assignment: 10/12/2021

Date Inspected: 10/12/2021

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Oct 2022)	
Parts:	N/A	HONDA NC750XA 745cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR7473D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE	Cut	32.00 F	*32.00 FL
2	1		*BAR HANDLE	Bent	266.00 F	*266.00 FL
3	2		*BOLT (PLASTIC)	Necessary	9.00 F	*9.00 FL
4	1		*BOX SIDE (GIVI) E22N (BLACK)	Cracked	388.00 F	*388.00 FL
5	1		*BRACKET HOLDER FIRE EXTINGUISHER	Bent	84.00 F	*84.00 FL
6	1		*BRACKET HOLDER SIDE BOX REAR LH	Bent	35.00 F	*35.00 FL
7	1		*BRACKET HOLDER SIDE BOX REAR RH	Bent	35.00 F	*35.00 FL
8	1		*BRACKET LED XT12 PEDESTAL MOUNT WITH KIT	Missing	65.00 F	*65.00 FL
9	1		*BRACKET MUDGUARD REAR	Broken	143.00 F	*143.00 FL
10	1		*BRACKET SIDE BOX (E21NC)	Bent	205.00 F	*205.00 FL
11	1		*BRACKET SIDE BOX SUPPORT	Bent	128.00 F	*128.00 FL
12	1		*CAP MASTER CYLINDER FRONT	Damaged	28.00 F	*28.00 FL
13	1		*CASE CHAIN	Bent	124.00 F	*124.00 FL
14	1		*CLAMP EXTENDER BAR HANDLE	Necessary	35.00 F	*35.00 FL
15	2		*COLLAR COVER WHEEL FRONT	Damaged	13.00 F	*13.00 FL
16	1		*COVER MUFFLER	Cut	220.00 F	*220.00 FL
17	1		*COVER TAIL LH	Cracked	298.00 F	*298.00 FL
18	1		*COVER TAIL RH	Cut	298.00 F	*298.00 FL
19	1		*CRASH BAR FRONT LH (CISCO)	Bent	135.00 F	*135.00 FL
20	1		*CRASH BAR LEG FRONT LH (CISCO)	Damaged	88.00 F	*88.00 FL
21	1		*CRASH BAR LEG FRONT RH (CISCO)	Bent	88.00 F	*88.00 FL
22	1		*CRASH BAR REAR LH (CISCO)	Bent	132.00 F	*132.00 FL
23	1		*CRASH BAR REAR RH (CISCO)	Bent	132.00 F	*132.00 FL
24	1		*FENDER REAR B	Broken	372.00 F	*372.00 FL
25	1		*GASKET MUFFLER	Necessary	26.00 F	*26.00 FL
26	1		*GRIP RAIL RH	Repair	352.00 F	*- FL
27	1		*GUARD ENGINE	Not Necessary	296.00 F	*- FL
28	1		*HOLDER STEP LH	Twisted	570.00 F	*570.00 FL
29	1		*HOLDER STEP RH	Bent	570.00 F	*570.00 FL
30	1		*LABEL CHAIN ADJUSTER	Necessary	26.00 F	*26.00 FL
31	1		*LABEL TIRE & DRIVE CHAIN	Necessary	26.00 F	*26.00 FL
32	1		*LAMP SIGNAL REAR LH	Broken	182.00 F	*182.00 FL
33	1		*LAMP SIGNAL REAR RH	Cut	182.00 F	*182.00 FL
34	1		*LEVER CLUTCH	Cut	54.00 F	*54.00 FL
35	1		*LIGHT LED (JL) 12 LED RED/BLUE WITH CLEAR LENS	Cracked	415.00 F	*415.00 FL
36	1		*LIGHT LED (JL) 8 LED RED LENS WITH TELESCOPIC POLE	Damaged	705.00 F	*705.00 FL
37	1		*MIRROR LH	Cut	145.00 F	*145.00 FL
38	1		*MUDGUARD REAR	Distorted	117.00 F	*117.00 FL
39	1		*MUFFLER COMP	Dented	808.00 F	*808.00 FL
40	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Broken	28.00 FS	*14.00 FS
41	2		*RIVET	Necessary	12.00 F	*12.00 FL
42	1		*RUBBER MOUNT LAMP SIGNAL LH	Necessary	22.00 F	*22.00 FL
43	1		*RUBBER MOUNT LAMP SIGNAL RH	Necessary	22.00 F	*22.00 FL
44	1		*STICKER (CERTIS CISCO) WINDSHIELD	Necessary	55.00 FS	*55.00 FS
45	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	28.00 FS	*12.00 FS
46	1		*SWINGARM SUB ASSY	Serviceable	2,405.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SWITCH (JL) SIREN REMOTE	Not Necessary	110.00 F	*- FL
48	3		*WASHER PLAIN 6MM	Necessary	19.50 F	*19.50 FL
49	1		*WHEEL SUB REAR	Repair	1,486.00 F	*- FL
50	1		*WINDSHIELD -CLEAR (PUIG)	Scratched	210.00 F	*210.00 FL
51	1		*CAMERA (V-SYS) M6 (WIFI VERSION)	Damaged	350.00 F	*350.00 FL
52	1		*STICKER (CERTIS CISCO) SIDE BOX DG LH	Necessary	235.00 FS	*235.00 FS
53	1		*STICKER (CERTIS CISCO) SIDE BOX DG RH	Necessary	235.00 FS	*235.00 FS
54	1		*STICKER (CERTIS CISCO) SIDE BOX LH NEW MODEL	Necessary	35.00 FS	*35.00 FS
55	2		*STICKER (CERTIS CISCO) SIDE BOX LOGO 2021	Necessary	50.00 FS	*50.00 FS
56	1		*STICKER (CERTIS CISCO) SIDE BOX REFLECTIVE LH	Necessary	70.00 FS	*70.00 FS
57	1		*STICKER (CERTIS CISCO) SIDE BOX REFLECTIVE RH	Necessary	70.00 FS	*70.00 FS
58	1		*STICKER (CERTIS CISCO) SIDE BOX RH NEW MODEL	Necessary	35.00 FS	*35.00 FS
59	5		*VELCRO (3M DUAL LOCK) CLEAR	Necessary	37.50 F	*37.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,342.00	8,663.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	785.20
Total Parts (\$\$)	13,342.00	7,877.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	1,512.00	500.00
2	REPAIR ON BODY ALIGNMENT	New	490.00	400.00
3	TRANSPORT CHARGES (MOTORCYCLE)	New	90.00	35.00
Gross Labour Cost (\$)			2,092.00	935.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >