



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPT

NO. : 39648

DATE : 07/12/2021
CLAIM NO. : 11829
POLICY NO. : D-21097290MFCE/117
FROM : RAYMOND

VEHICLE NO. : FBR7473D
MAKE/MODEL : HON / NC750X

*not Ashraf
10/12/21
P/P \$
7 days
To be ph. After 4pm*

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 40187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
2	BAR HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$266.00	266.00
3	BOLT (PLASTIC) P/N: 22353 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50	9.00
4	BOX SIDE (GIVI) E22N (BLACK) P/N: 49418 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00
5	BRACKET HOLDER FIRE EXTINGUISHER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	84.00
6	BRACKET HOLDER SIDE BOX REAR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
7	BRACKET HOLDER SIDE BOX REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
8	BRACKET LED XT12 PEDESTAL MOUNT WITH KIT P/N: 62717 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	65.00
9	BRACKET MUDGUARD REAR P/N: 66744 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$143.00	143.00

*39648 *



S/N	Description	Action	Qty	Unit Price	Amount
10	BRACKET SIDE BOX (E21NC) P/N: 42174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$205.00	205.00 <i>Sent</i>
11	BRACKET SIDE BOX SUPPORT P/N: 71745 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$128.00	128.00 <i>Sent</i>
12	CAP MASTER CYLINDER FRONT P/N: 45603 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 ?
13	CASE CHAIN P/N: 57620 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	124.00 <i>Sent</i>
14	CLAMP EXTENDER BAR HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 <i>nm</i>
15	COLLAR COVER WHEEL FRONT - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.50	13.00 ?
16	COVER MUFFLER P/N: 58549 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$220.00	220.00 <i>nm</i>
17	COVER TAIL LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$298.00	298.00 <i>nm</i>
18	COVER TAIL RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$298.00	298.00 <i>nm</i>
19	CRASH BAR FRONT LH (CISCO) P/N: 70597 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$135.00	135.00 <i>Sent</i>
20	CRASH BAR LEG FRONT LH (CISCO) P/N: 70599 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$88.00	88.00 <i>nm</i>
21	CRASH BAR LEG FRONT RH (CISCO) P/N: 70600 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$88.00	88.00 <i>Sent</i>
22	CRASH BAR REAR LH (CISCO) P/N: 70601 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00 <i>Sent</i>
23	CRASH BAR REAR RH (CISCO) P/N: 70602 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00 <i>nm</i> X
24	FENDER REAR B P/N: 57702 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$372.00	372.00 <i>nm</i>

*39648 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price		Amount	
25	GASKET MUFFLER P/N: 61399 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	11	26.00	X
26	GRIP RAIL RH P/N: 57696 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$352.00	2	352.00	X
27	GUARD ENGINE P/N: 66969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$296.00	11	296.00	X
28	HOLDER STEP LH P/N: 57701 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$570.00	121	570.00	
29	HOLDER STEP RH P/N: 57714 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$570.00	?	570.00	
30	LABEL CHAIN ADJUSTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	ner	26.00	
31	LABEL TIRE & DRIVE CHAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	ner	26.00	
32	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	24.00	\$63.00	500	1,512.00	
33	LAMP SIGNAL REAR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00	520	182.00	
34	LAMP SIGNAL REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00	617	182.00	
35	LEVER CLUTCH P/N: 65115 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	617	54.00	
36	LIGHT LED (JL) 12 LED RED / BLUE WITH CLEAR LENS P/N: 62716 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$415.00	612	415.00	
37	LIGHT LED (JL) 8 LED RED LENS WITH TELESCOPIC POLE P/N: 67025 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$705.00	712	705.00	
38	MIRROR LH P/N: 57708 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$145.00	617	145.00	
39	MUDGUARD REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$117.00	715	117.00	

*39648 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	MUFFLER COMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$808.00	808.00
41	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
42	REPAIR ON BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$490.00	490.00
43	RIVET P/N: 29942 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	12.00
44	RUBBER MOUNT LAMP SIGNAL LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
45	RUBBER MOUNT LAMP SIGNAL RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
46	STICKER (CERTIS CISCO) WINDSHIELD P/N: 67401 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
47	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
48	SWINGARM SUB ASSY P/N: 58570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,405.00	2,405.00
49	SWITCH (JL) SIREN REMOTE P/N: 66584 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$110.00	110.00
50	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - BIKE TOWED BACK TO BHH		1.00	\$90.00	90.00
51	WASHER PLAIN 6MM - (REPORTED BY MECHANIC)	REPLACE	3.00	\$6.50	19.50
52	WHEEL SUB REAR P/N: 57718 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,486.00	1,486.00
53	WINDSHIELD - CLEAR (PUIG) P/N: 67016 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00

SUB TOTAL

GST @ 7 %

GRAND TOTAL (SGD)

\$14,316.50

\$1,002.16

\$15,318.66

*39648 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*39648 *

bizSAFE₃

