

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012538/EGA3Q2**Date:** 14/04/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0007747
Claimant Vehicle No :	SHC430G	Insured Vehicle No :	SMV2645G
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005425

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC430G	Engine No:	G4LEJU191238
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU141322
Reg. Date:	30/04/2019 (Man. Year: 2018)	Odometer:	210795 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,193.12	1,010.88	4,182.24	80.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,150.00	2,650.00	69.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,993.12	2,160.88	6,832.24	75.97
+ GST 7.00/7.00% (S\$)	629.52	151.26	478.26	75.97
Nett Amount (S\$)	9,622.64	2,312.14	7,310.50	75.97
+ Loss of Use (5.0 x S\$40.00/day) (S\$)		200.00		
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,119.59		
Global Sum Settlement (S\$)		3,110.00		

INSPECTION

Date of Assignment:	10/12/2021	
Date Inspected:	13/12/2021	Inspected At: Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2022)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC430G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Dented	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTER MOULDING	Broken	270.10 FL	*270.10 FL
3	1		*REAR LH BUMPER RETAINER	Broken	33.10 FL	*33.10 FL
4	1		*REAR BUMPER LOWER MOULDING	Cut	47.50 FL	*47.50 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
6	1		*REAR LH BUMPER REINFORCEMENT BRACKET	Not Necessary	138.10 FL	*- FL
7	1		*REAR BUMPER TOWING COVER	Missing	9.10 FL	*9.10 FL
8	1		*REAR FOG LAMP ASSY	Not Necessary	201.50 FL	*- FL
9	1		*REAR LH BUMPER UNDER COVER	Not Necessary	35.90 FL	*- FL
10	1		*REAR LH BUMPER REFLECTOR	Cut	31.90 FL	*31.90 FL
11	1		*SMART KEY ANTENNA	Not Necessary	41.90 FL	*- FL
12	1		*REAR TAILGATE HYUNDAI EMBLEM	Not Necessary	68.20 FL	*- FL
13	1		*REAR TAILGATE IONIQ EMBLEM	Not Necessary	48.20 FL	*- FL
14	1		*REAR TAILGATE HYBRID EMBLEM	Not Necessary	51.20 FL	*- FL
15	1		*REAR BOOT WEATHERSTRIP	Not Necessary	127.40 FL	*- FL
16	1		*TAILLAMP LH	Not Necessary	905.20 FL	*- FL
17	1		*REAR LH FENDER LINER	Not Necessary	148.40 FL	*- FL
18	1		*REAR LH QUARTER PANEL AIR VENT	Not Necessary	57.60 FL	*- FL
19	1		*REAR LH BLIND SPOT DETECTION UNIT	Not Necessary	1,784.40 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*30.00 FS
21	1		*REAR BUMPER PROTECTOR	Necessary	160.00 FS	*60.00 FS
22	2		*SET REAR REVERSE SENSOR	Broken	400.00 FS	*200.00 FS
23	1		*SET REAR FENDER LINER CLIP	Necessary	65.00 FS	*30.00 FS
24	1		*REAR TAILGATE 6552-1111 STICKER	Not Necessary	140.00 FS	*- FS
25	1		*REAR TAILGATE COMFORT DELGROSTICKER	Not Necessary	140.00 FS	*- FS
26	1		*REAR TAILGATE BOOK NOW STICKER	Not Necessary	140.00 FS	*- FS
27	1		*SET REAR BUMPER MOULDING CLIP	Necessary	55.00 FS	*10.00 FS
28	1		*SET REAR BUMPER UNDER COVER CLIP	Not Necessary	60.00 FS	*- FS
29	1		*SET TAILLAMP GUIDE CLIP	Not Necessary	55.00 FS	*- FS
30	1		*REAR LICENCE PLATE NUMBER WITH FRAME	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,143.90	1,181.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	950.78	170.22
Total Parts (\$\$)	5,193.12	1,010.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	1,200.00	400.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	170.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	280.00	0.00
4	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	260.00	30.00
5	TO REFIT REAR REVERSE SENSOR	New	140.00	30.00
6	TO RESPRAY REAR BUMPER	New	250.00	200.00
7	TO RESPRAY REAR BUMPER CENTER MOULDING	New	250.00	150.00
8	TO RESPRAY REAR BUMPER LOWER MOULDING	New	250.00	80.00
9	TO RESPRAY REAR REVERSE SENSOR	New	250.00	30.00
10	TO RESPRAY REAR END PANEL	New	250.00	200.00
11	TO RESPRAY REAR TAILGATE PANEL	New	250.00	0.00
12	TO RESPRAY REAR QUARTER PANEL	New	250.00	0.00
Gross Labour Cost (\$\$)			3,800.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >