

Our Job Ref No : 305497436
Date : 11/12/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHC3309E


Fax :


Date of Accident : 09/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- SMT1403E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$494.72
 - (b) Labour Charges (include advertisement stickers etc,if any) \$630.00
 - Total for Part-By-Part Repair Cost** \$1,124.72
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less. 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 15/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 9-Dec-21

MODEL: Hyundai Ioniq

VEHICLE NO.: SHC3309E

INSURANCE: CHINA TAIPINGMVA: LIM T S

SAS-KIV

LKK - Thevan

CP/P

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$459.40
	Rear Bumper Centre Moulding	1		\$451.25
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Wheel Cap LH	1		\$346.40
	SUB TOTAL			\$1,279.05
	LESS 20%			\$255.81
	DISCOUNTED TOTAL			\$1,023.24
	Rear Fender Adv. Sticker RH / LH	2	\$100.00	\$200.00
	SUB S/NETT TOTAL			\$200.00
	SPARE PARTS TOTAL			\$1,223.24
	Labour Charge			
	Panel Beating			\$400.00
	Spray Painting Charge			\$300.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,043.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan@lhauto.com

82235769

9/12/21 1645

P/p bfr paint photo
2 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 10.12.2021

Time: 13:44:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305497436
REGN NO : SHC3309E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 09.12.2021 12:40
ACCIDENT DATE : 09.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0111-G REAR BUMPER CLIPS 10 L 22.00 20.00 17.60
0002 03-01-0104-2137-G REAR WHEEL CAP LH 1 346.40 20.00 277.12

SUB-TOTAL : 294.72

JOB NATURE

0000 PB PANEL BEATING-SHC3309E 350.00
0001 SP SPRAYPAINT CHARGE 250.00
0002 L R/I REVERSE SENSORS 30.00
0003 20-05 Rear Fender Adv.Sticker RH/LH 200.00

SUB-TOTAL : 830.00

TOTAL : 1,124.72


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO