

ASS. REC. BY:

Steve

REF:

CS/AG121012543/EFf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STY 9028L Yr Regn: 13/10/10Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato c.c. 1591Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 240944 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFY411LA5171110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 6/12/21 D.O.I. 14/12/21Survey held at Win Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-27K

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

WIN AUTOMOTIVE SERVICES

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJY 9028L KIA CERATO FORTE

Adjustment of Spare Parts Costs for Repairs			
Item	Qty	Vehicle parts description	Estimate by
1	1	rear bumper ? disassemble ?	620.00
2	1	rear bumper side retainer LH ?	37.00
3	1	rear bumper reinforcement X	320.00
4	1 set	rear bumper fasteners X	38.00
5	1	rear bumper sponge X	155.00
16	1	bootlid lamp LH X	195.00
17	1 set	taillamp clips X	16.00
18	1	taillamp LH X	300.00
24	1	RR door LH X R	795.00
25	1	RR door hindge upper LH X	55.00
26	1	RR door hindge lower LH X	55.00
27	1	RR door outer moulding LH X	95.00
28	1	RR door weatherstrip LH X	185.00
29	1	RR outer handle LH X	95.00
30	1	RR door inner lock LH X	285.00
31	1	RR outer key cylinder LH X	235.00
32	1	RR door inner trim board LH X	595.00
33	1	RR door inner trim board clips X	18.00
34	1	RR door frame garnish LH X	38.00
35	1	RR door window glass LH X	265.00
36	1	RR door window glass guide LH X	54.00
37	1	RR window regulator LH X	495.00
38	1	RR window regulator motor LH X	395.00
39	1	rear LH fender X R	920.00
40	1	rear LH fender inner trim X	265.00
41	1	rear LH fender inner trim fasteners X	28.00
42	1	rear LH fender inner sheild X	185.00
43	1	rear LH fender inner sheild fasteners X	32.00
44	1	rear LH rocker panel X	750.00
	1	rear LH shock absorber X ?	385.00
	1	rear LH wheel bearing	310.00
	1	rear LH lower arm Y	335.00
			8551.00
Less 10%			1710.2
			6840.80

		Special nett item	
4	1	reverse sensor X	200.00
5	1	rear LH tyre rim / MT	300.00 250 ✓
6	1	rear LH tyre X	200.00
7	1	rear LH window moulding X	110.00
		Total parts	810.00

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and expandable	800.00	600
Carry out body cavity preservation	100.00	30
To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat	800.00	500
Check wiring	60.00	30
Remove & reinstall reverse sensor	60	30
to remove and reinstall rear LH door components	80	X
Remove & reinstall rear boot upholstery	100	X
to perform 4 wheel alignment	100	60
remove and reinstall rear LH undercarriage item	200	100
remove and reinstall rear windscreen	150	X

Total labour 2450.00

Steve (LKK)

14/12/21, 9.10c

HL 10

LI

17 11 11

4 4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: