

ASS. REC. BY:

Steve

REF:

CS/AG121012543/EF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJU 702D

Policy No. _____

Claims No. C10012837/KY

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJY 9028L Yr Regn: 13/10/10

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: KIA Cerato c.c. 1591

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 240944 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFY411LA5171110

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 6/12/21 D.O.I. 14/12/21

Survey held at Win Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear LH

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|---|
| | MV-27K |
| 21/12/21 | LS \$2000 confirmed by email (Red 8100.80, 80%) |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to?

☐ : Prell. Report

1)

Date/Time, File Return to?

☐ : Final Report

2) 21/12/21-typist

Report Format : TP

Lump Sum / L.B.H. (\$ 2000)

Days Of Repair: 4

Resurvey No. of Trlp: 2

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

WIN AUTOMOTIVE SERVICES

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJY 9028L KIA CERATO FORTE

| Adjustment of Spare Parts Costs for Repairs | | | |
|---|-------|---|----------------|
| Item | Qty | Vehicle parts description | Estimate by |
| 1 | 1 | rear bumper ? disassemble | 620.00 |
| 2 | 1 | rear bumper side retainer LH ? | 37.00 |
| 3 | 1 | rear bumper reinforcement X | 320.00 |
| 4 | 1 set | rear bumper fasteners X | 38.00 |
| 5 | 1 | rear bumper sponge X | 155.00 |
| 16 | 1 | bootlid lamp LH X | 195.00 |
| 17 | 1 set | taillamp clips X | 16.00 |
| 18 | 1 | taillamp LH X | 300.00 |
| 24 | 1 | RR door LH X R | 795.00 |
| 25 | 1 | RR door hidge upper LH X | 55.00 |
| 26 | 1 | RR door hidge lower LH X | 55.00 |
| 27 | 1 | RR door outer moulding LH X | 95.00 |
| 28 | 1 | RR door weatherstrip LH X | 185.00 |
| 29 | 1 | RR outer handle LH X | 95.00 |
| 30 | 1 | RR door inner lock LH X | 285.00 |
| 31 | 1 | RR outer key cylinder LH X | 235.00 |
| 32 | 1 | RR door inner trim board LH X | 595.00 |
| 33 | 1 | RR door inner trim board clips X | 18.00 |
| 34 | 1 | RR door frame garnish LH X | 38.00 |
| 35 | 1 | RR door window glass LH X | 265.00 |
| 36 | 1 | RR door window glass guide LH X | 54.00 |
| 37 | 1 | RR window regulator LH X | 495.00 |
| 38 | 1 | RR window regulator motor LH X | 395.00 |
| 39 | 1 | rear LH fender X R | 920.00 |
| 40 | 1 | rear LH fender inner trim X | 265.00 |
| 41 | 1 | rear LH fender inner trim fasteners X | 28.00 |
| 42 | 1 | rear LH fender inner sheild X | 185.00 |
| 43 | 1 | rear LH fender inner sheild fasteners X | 32.00 |
| 44 | 1 | rear LH rocker panel X | 750.00 |
| | 1 | rear LH shock absorber X ? | 385.00 |
| | 1 | rear LH wheel bearing | 310.00 |
| | 1 | rear LH lower arm Y | 335.00 |
| | | | 8551.00 |
| Less 10% | | | 1710.2 |
| | | | 6840.80 |

| | | | |
|---|---|---------------------------|---------------|
| | | Special nett item | |
| 4 | 1 | reverse sensor X | 200.00 |
| 5 | 1 | rear LH tyre rim / MT | 300.00 250 ✓ |
| 6 | 1 | rear LH tyre X | 200.00 |
| 7 | 1 | rear LH window moulding X | 110.00 |
| | | Total parts | 810.00 |

Adjustment of Labour Costs for Repairs

| | | |
|---|--------|-----|
| Supply paint material to the rear and expandable | 800.00 | 600 |
| Carry out body cavity preservation | 100.00 | 30 |
| To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat | 800.00 | 500 |
| Check wiring | 60.00 | 30 |
| Remove & reinstall reverse sensor | 60 | 30 |
| to remove and reinstall rear LH door components | 80 | X |
| Remove & reinstall rear boot upholstery | 100 | X |
| to perform 4 wheel alignment | 100 | 60 |
| remove and reinstall rear LH undercarriage item | 200 | 100 |
| remove and reinstall rear windscreen | 150 | X |

Total labour 2450.00

Steve (LKK)

14/12/21, 9.10c

HL 10

LH

14 11 11

4 4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: