

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21012544/R1TF3E2

Date: 10/03/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070149442
Claimant Vehicle No : SMB3123U Insured Vehicle No : GBA6666K
Date of Loss: 05/12/2021 Nature of Claim: TP Claim No: 2550112433SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB3123U**
Make & Model: MAN A22, 10.5 D (A) Engine No: 50339831023982
Reg. Date: 04/05/2015 (Man. Year: 2014) Chassis No: WMAA22ZZ9F7002666
Colour: Multi-colour Odometer: 400681 km
Engine Capacity: 10518 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,937.00	2,937.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,218.00	1,026.00	192.00	15.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,155.00	3,963.00	192.00	4.62
+ GST 7.00/7.00% (S\$)	290.85	277.41	13.44	4.62
Nett Amount (S\$)	4,445.85	4,240.41	205.44	4.62

INSPECTION

Date of Assignment: 13/12/2021
Date Inspected: 13/12/2021 Inspected At: SBS Transit Ltd (YCK)
3 Yio Chu Kang Crescent
Singapore 786010
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LENS-R-PAINTED 501674.REAR FRP	Cracked	38.00 F	*38.00 F
2	1		*LENS-R-PAINTED 501675.REAR FRP	Necessary	38.00 F	*38.00 F
3	10		*ROUND PLUG SLEEVE;4MM;DIA	Necessary	2.00 F	*2.00 F
4	10		*ROUND PLUG;4MM;DIAMETER	Necessary	2.00 F	*2.00 F
5	2		*CATCH LOCK.BRKT B.REAR BUMPER	Necessary	26.00 F	*26.00 F
6	1		*LED.SIGNAL LAMP.RR.LH/RH	Cracked	151.00 F	*151.00 F
7	2		*BUMPER BRKT	Bent	30.00 F	*30.00 F
8	1		*BUMPER.REAR CENTER.REAR FRP	Cracked	650.00 F	*650.00 F
9	1		*COVER.REAR LAMP.O/S	Cracked	340.00 F	*340.00 F
10	1		*DOOR.COMPLETE.C SERIES.RR ENG	Deformed	1,300.00 F	*1,300.00 F
11	1		*BUMPER.STEEL.RR	Bent	150.00 F	*150.00 F
12	2		*LED.TAIL/STOP LAMP.RR.LH/RH	Cracked	210.00 F	*210.00 F
F=Franchise part.						
					Total Parts (\$\$)	2,937.00 2,937.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT - GREEN;5L;SG BUS	New	36.00	36.00
2	CONTRACTOR LABOUR COST	New	890.00	890.00
3	WORKSHOP ASSESSMENT LABOUR COST	New	192.00	0.00
4	LIVERY / ADVERTISEMENT COST	New	100.00	100.00
5	TOWING COST (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			1,218.00	1,026.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >