

(08/11/13) wef

ASS. REC. BY: Ram

REF:

CS/AH 2101254.4/R1/f3

FEH 653m

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 31234

at Workshop m/s SBS

of 3,410 CHUKANK RD

Insured:

ALH

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMB 31234

Yr Regn:

2015 / MMY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN NL320F(A22)

c.c 16518

Colour

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

400 681

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMAA 2229F 700 2666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

22 0/P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

05/12/21

D.O.I.

13/12/21

Survey held at

SBS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SUBMIT \$3963, 3DAYS

RED: 192;4%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

3rd Party
Soon Bee Vehicle & Bodywork Maintenance

1000 Anson Road #33-17 International Plaza Singapore 079903.
Tel: 90036715 Fax: 62256130 Email: soonbee_vehicle@yahoo.com.sg
SBS Transit Registration No: 53076555A

Our Ref No. : SB-SE20054





Date: 06-Dec-21

Seletar Workshop.
No. 3 Yio Chu Kang Crescent
Singapore 786010
TO : Mr Nurizman

QUOTATION FOR ACCIDENT REPAIR FOR BUS NO.

SMB3123U

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Seletar Workshop.

1)	Vehicle No : Model :	SMB3123U SD
2)	Total Cost :	- Labour Cost : \$ 890.00 GST (7%) : \$ 62.30 Total : \$ 952.30
	Service Description:	<p>Work Scopes</p> <p>Dismantle and replace rear center bumper Dismantle and replace o/s/r corner bumper Dismantle and replace rear number plate light Dismantle and replace o/s/r tail light assy Repair rear bumper undercarriage cross member Repair rear engine cover lock mechanism Dismantle and replace rear engine cover red reflector Touch up putty on accident area Respray accident area</p> <div></div> <p>Supply workers for 23 ManHour</p> <p>TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES Vehicle Electric and wiring system not included</p> <p>(B) Materials and Parts: - Supply by SBS Transit</p> <p>C) Mechanical/Engine Effect - NA</p>

Note: Quotation valid for 1 Month only

This is a computer-generated document. No signature will be required.

NURIZMAN BIN YUSOFF
TECHNICAL OFFICER
SELETAR BUS WORKSHOP

09 DEC 2021

REPORT-ID : TAC019R
USER-ID : edsfof02

ACCIDENT REPORT

DATE : 09/12/2021 16:27:05

Page : 1 of 2

79408-181

Company	SBS	District	SE	IP NUMBER	
Duty IO	NORLELA A. YUSOFF	Report No.	E/5289/2021	Accident Date	05/12/2021
Report Date	09/12/2021	Shift Code	PM SHIFT	Accident Time	16:34
Place of Accident	YISHUN AVE. 6 ROAD AND YISHUN AVE. 7 ROAD JUNCTION				
Road Name	YISHUN AVE. 6 ROAD	Road Name	YISHUN AVE. 7 ROAD		
Accident Type	TRAFFIC	Final Cause			
Weather Code	CLEAR	Nature Of Accident	MINOR		
Operating Hours	WORKED 1 HR 30 MINS	Road Surface	DRY		
Traffic Volume	MODERATE	Type Of Location	CONTROLLED X-JUNCTION		
Traffic Control	TRAFFIC LIGHT CONTROLLED	Traffic Flow	TWO WAYS		
Collision With	VEHICLE	Ambulance Convey	N		
Fatal	0	Type Of Collision	REAR BEING HIT		
Police Report	Y	Serious Injury	0	Minor Injury	0
Bus Towed	N	Police Report Number	F/20211206/2047	Photo Taken	Y
Urgent CBR Status	N	Sketch	Y	Mechanical Fault	N
Damage To Bus	SMB3123U - REAR DMG	CFMS Case	N	CFMS No	

Facts of Incident I stopped on the left most lane along Yishun Ave. 6 road at the traffic junction with Yishun Ave. 7 road. The traffic light was red. Suddenly I felt a collision from the rear. I discovered a lorry (GBA6666K) had collided onto the rear of my bus. At that point of time there were 4 passengers in my bus, I enquired with them and they told me that they were fine. Afterwhich, I exchanged particulars with the lorry driver and he informed me that he could not stop on time resulted in the accident. The bus 's rear was dented. That 's all .

Brief Particulars NA

Reason for Late Report

STATEMENT READ OVER TO ME

AND I AFFIRM IT TO BE TRUE AND CORRECT

SIGNATURE OF STAFF

THAM MENG KHUAN
Safety Officer
Seletar Depot

NAME AND DESIGNATION OF RECORDER

3P.