

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21012547/ETF3E2

**Date:** 04/01/2022

### REFERENCE

Insured/Claimant:	LIM SENG CHOON	Policy No:	1900011407		
Date of Loss:	09/12/2021	Nature of Claim:	OD	Claim No:	0504818296SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ144L	Engine No:	3A92UHM3342
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Chassis No:	MMBSTA13AKH000687
Reg. Date:	20/02/2019 (Man. Year: 2018)	Odometer:	60570 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,979.00	2,787.33	4,191.67	60.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	2,810.00	2,750.00	49.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,539.00</b>	<b>5,597.33</b>	<b>6,941.67</b>	<b>55.36</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>12,239.00</b>	<b>5,297.33</b>	<b>6,941.67</b>	<b>56.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>856.73</b>	<b>370.81</b>	<b>485.92</b>	<b>56.72</b>
<b>Nett Amount (S\$)</b>	<b>13,095.73</b>	<b>5,668.14</b>	<b>7,427.59</b>	<b>56.72</b>

### INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	13/12/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Dented	706.00 F	*706.00 FL
4	1		*MARK, THREE-DIA	Necessary	70.00 F	*70.00 FL
5	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	62.00 F	*- FL
6	1		*BRACKET, FR BUMPER, RH	Not Necessary	13.00 F	*- FL
7	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 F	*- FL
8	1		*GRILLE, FR UNDER	Broken	165.00 F	*165.00 FL
9	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 F	*- FL
10	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 F	*- FL
11	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 F	*- FL
12	1		*GRILLE, RADIATOR	Broken	557.00 F	*557.00 FL
13	1		*PANEL ASSY, FR END	Dented	1,055.00 F	*1,055.00 FL
14	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	66.00 F	*- FL
15	1		*HEADLAMP ASSY, RH	Not Necessary	663.00 F	*- FL
16	1		*HEADLAMP ASSY, LH	Not Necessary	663.00 F	*- FL
17	1		*PANEL, AIR GUIDE	Broken	112.00 F	*112.00 FL
18	1		*RADIATOR ASSY	Not Necessary	972.00 F	*- FL
19	1		*TANK ASSY, RADIATOR COND	Not Necessary	42.00 F	*- FL
20	1		*FAN, COOLING, LH	Not Necessary	77.00 F	*- FL
21	1		*SHROUD, COOLING FAN	Not Necessary	131.00 F	*- FL
22	1		*CONDENSER ASSY, A/C REFRIGE	Dented	762.00 F	*762.00 FL
23	1		*PIPE, A/C CONDENSER OUTLET	Not Necessary	305.00 F	*- FL
24	1		*HOSE, A/C COMPR DISCHARGE	Not Necessary	210.00 F	*- FL
25	1		*RIVET, FR BUMPER (X10)	Necessary	50.00 F	*50.00 FL
			(Supplementary)			
26	1		*CLIPS (X10)	Necessary	30.00 F	*30.00 FL
			(Supplementary)			
27	1		*PANEL, AIR GUIDE, RH	Broken	11.00 F	*11.00 FL
			(Supplementary)			
28	1		*PANEL, AIR GUIDE, LH	Broken	11.00 F	*11.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,979.00	3,599.00
- List Item Discount on L Items 0.00/23.00% (S\$)	0.00	811.67
Total Parts (S\$)	6,979.00	2,787.33

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR FRT FENDER RH & LH BONNET	New	1,800.00	450.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL FRT FENDER RH & LH	New	1,750.00	350.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	TOP UP AIRCON GAS	New	80.00	80.00
7	REPLACE FRONT AIR DAM (Supplementary)	New	80.00	80.00
8	RESPRAY FRONT AIR DAM (Supplementary)	New	350.00	350.00
9	RESPRAY FRONT H/LAMP SUPPORT PANEL (Supplementary)	New	350.00	350.00
10	REPLACE FRONT H/LAMP SUPPORT PANEL (Supplementary)	New	900.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,560.00</b>	<b>2,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >