

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012549/T1EA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700035208
Claimant Vehicle No :	SH7982C	Insured Vehicle No :	SLR1760X
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	1846909396SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7982C		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFDU580795
Reg. Date:	29/12/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU097349
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,987.72	3,139.12	848.60	21.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	980.00	300.00	23.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,267.72	4,119.12	1,148.60	21.80
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	5,267.72	3,300.00	1,967.72	37.35
+ GST 7.00/7.00% (S\$)	368.74	231.00	137.74	37.35
Nett Amount (S\$)	5,636.46	3,531.00	2,105.46	37.35
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$110.67/day) (S\$)		221.34		
(S\$)		3,852.34		
Liable Amount (50.00%) (S\$)		1,926.17		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,928.17		
Global Sum Settlement (S\$)		1,920.00		

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	13/12/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER BRACKET RH	Deformed	24.60 FL	*24.60 FL
2	1		*FRONT BUMPER TOP BRACKET RH	Not Necessary	22.40 FL	*- FL
3	1		*FRONT BUMPER	Deformed	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER GRILLE -RH	Not Necessary	93.45 FL	*- FL
5	1		*RADIATOR EMBLEM	Necessary	28.00 FL	*28.00 FL
6	1		*RADIATOR GRILLE ASSY	Cracked	1,409.10 FL	*1,409.10 FL
7	1		*HEAD LAMP SUPPORT PANEL	Not Necessary	907.40 FL	*- FL
8	1		*HEAD LAMP ASSY /RH	Cut	1,388.00 FL	*1,388.00 FL
9	10		*BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,977.15	3,923.90
- List Item Discount on L Items 20.00/20.00% (S\$)	989.43	784.78
Total Parts (S\$)	3,987.72	3,139.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	560.00	420.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TUFF KOTE	New	60.00	30.00
4	CHECK LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,280.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >