

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012550/EVF3N2**Date:** 10/01/2022**REFERENCE**

Insured/Claimant: LEK CHIN KWONG (LU ZENGGUANG)
Date of Loss: 10/12/2021

Policy No: 1900246247-01
Nature of Claim: OD

Claim No: 9820821775SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR7700T	Engine No:	G4KJJH768945
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAPH813ML5612855
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	19135 km
Colour:	Black		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	S\$121,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,238.40	5,453.60	1,784.80	24.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,460.00	1,400.00	36.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,098.40	7,913.60	3,184.80	28.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	10,498.40	7,313.60	3,184.80	30.34
+ GST 7.00/7.00% (S\$)	734.89	511.95	222.94	30.34
Nett Amount (S\$)	11,233.29	7,825.55	3,407.74	30.34

INSPECTION

Date of Assignment: 13/12/2021

Date Inspected: 13/12/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-HOOD	Dented	1,654.00 FL	*1,654.00 FL
2	1		*HINGE ASSY-HOOD,LH	Not Necessary	87.00 FL	*- FL
3	1		*HINGE ASSY-HOOD,RH	Not Necessary	87.00 FL	*- FL
4	13		*CLIP-HOOD INSULATING PAD MTG	Not Necessary	13.00 FL	*- FL
5	1		*LATCH ASSY-HOOD	Not Necessary	104.00 FL	*- FL
6	1		*STRIP ASSY-FR-HOOD	Not Necessary	27.00 FL	*- FL
7	1		*LAMP ASSY-HEAD,RH	Broken	2,743.00 FL	*2,743.00 FL
8	1		*CARRIER ASSY-FRONT END MODULE	Broken	760.00 FL	*760.00 FL
9	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	551.00 FL	*- FL
10	1		*COVER-FR BUMPER UPR	Broken	561.00 FL	*561.00 FL
11	1		*MOULDING-FRONT BUMPER,LWR,RH	Broken	89.00 FL	*89.00 FL
12	1		*LIP-FRONT BUMPER	Not Necessary	56.00 FL	*- FL
13	1		*SKID PLATE-FR BUMPER	Broken	111.00 FL	*111.00 FL
14	1		*GRILLE-FRONT BUMPER	Not Necessary	191.00 FL	*- FL
15	1		*GRILLE-FRONT BUMPER FOG LAMP,R	Broken	81.00 FL	*81.00 FL
16	1		*AIR-DUCT-FR BUMPER,RH	Not Necessary	28.00 FL	*- FL
17	1		*LAMP ASSY-FRONT FOG,RH	Broken	593.00 FL	*593.00 FL
18	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	117.00 FL	*- FL
19	1		*STIFFENER ASSY-FR BUMPER LWR	Not Necessary	117.00 FL	*- FL
20	1		*BRACKET-FR BUMPER SIDE,RH	Not Necessary	17.00 FL	*- FL
21	1		*GARNISH ASSY-FNDR SIDE,RH	Not Necessary	88.00 FL	*- FL
22	4		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	748.00 FL	*- FL
23	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
24	1		*RESERVOIR & PUMP ASSY-WASHER (Supplementary)	Crushed	170.00 FL	*170.00 FL
25	1		*TANK ASSY-RESERVOIR (Supplementary)	Crushed	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,043.00	6,812.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,804.60	1,358.40
Total Parts (\$)	7,238.40	5,453.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ULTRASONIC SENSOR-S.P.A.S SIDE	New	0.00	0.00
2	RENEW FR BUMPER,BONNET & FR SUPPORT REPAIR RHF FENDER	New	2,000.00	600.00
3	RESPRAY FR BUMPER,BONNET & RHF FENDER	New	1,050.00	1,050.00
4	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TOP UP AC GAS	New	80.00	80.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	REMOVE & REFIT FR PARKING ASSIST SENSOR	New	80.00	80.00
9	REPLACE FRONT SUPPORT PANEL	New	400.00	400.00
Gross Labour Cost (\$\$)			3,860.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >