

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21012551/UTF3E2

**Date:** 22/12/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070132615  
Claimant Vehicle No : SNC5764P Insured Vehicle No : SMV384Y  
Date of Loss: 09/12/2021 Nature of Claim: TP Claim No: 2129668950SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC5764P**  
Make & Model: BMW X1, 1.5 SDRIVE 18I (A) Engine No: 38215616B38B15A  
Reg. Date: 30/05/2019 (Man. Year: 2019) Chassis No: WBAJG120905N05652  
Colour: White Odometer: 39143 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 13/12/2021  
Date Inspected: 13/12/2021 Inspected At: Khek Joo Motor Workshop (HQ)  
BLK 9004 TAMPINES STREET 93 #01-94  
Singapore 528838  
Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$115,000.00 (EST)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
2	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
3	1		*REAR WINDSCREEN INNER SEAL	Necessary	0.00 F	*- F
4	1		*TAILGATE	Dented	0.00 F	*- F
5	1		*TAILGATE REAR LOGO	Necessary	0.00 F	*- F
6	1		*TAILGATE X1 EMBLEM	Necessary	0.00 F	*- F
7	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
8	1		*REAR BUMPER TOP	Deformed	0.00 F	*- F
9	1		*REAR BUMPER BOTTOM	Distorted	0.00 F	*- F
10	1		*REAR BUMPER DIFFUSER	Deformed	0.00 F	*- F
11	1		*REAR BUMPER PDC SENSOR	Shorted	0.00 F	*- F
12	1		*REAR BUMPER BEAM	Repair	0.00 F	*- F
13	1		*REAR BUMPER INNER RETAINER	Cracked	0.00 F	*- F
14	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
15	1		*REAR END PANEL	Repair	0.00 F	*- F
16	1		*REAR BUMPER TOP MOULDING	Dented	0.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**

**0.00**

**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**