

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012552/EVF3N2**Date:** 24/01/2022**REFERENCE**

Insured/Claimant:	LAM SZE JIA (LAN SIJIA)	Policy No:	1900150108
Date of Loss:	10/12/2021	Nature of Claim:	OD Claim No: 6063513750SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN5700C	Engine No:	4J11BH4181
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0601876
Reg. Date:	19/08/2019 (Man. Year: 2019)	Odometer:	27191 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,587.98	2,498.58	2,089.40	45.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,430.00	530.00	27.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,547.98	3,928.58	2,619.40	40.00
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	6,147.98	3,528.58	2,619.40	42.61
+ GST 7.00/7.00% (S\$)	430.36	247.00	183.36	42.61
Nett Amount (S\$)	6,578.34	3,775.58	2,802.76	42.61

INSPECTION

Date of Assignment:	13/12/2021	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Date Inspected:	14/12/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY,FOG,FR RH	Not Necessary	348.00 FL	*- FL
2	1		*GARNISH,FR BUMPER,RH	Not Necessary	48.00 FL	*- FL
3	1		*BRACKET,FR BUMPER SIDE,RH	Not Necessary	18.00 FL	*- FL
4	1		*GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
5	1		*GARNISH,FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
6	1		*MOULDING,FR BUMPER,RH	Not Necessary	116.00 FL	*- FL
7	1		*FACE,FR BUMPER	Broken	851.00 FL	*851.00 FL
8	1		*COVER,FR BUMPER	Cut	361.00 FL	*361.00 FL
9	1		*GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
10	10		*RIVET,FR BUMPER	Necessary	50.00 FL	*50.00 FL
11	1		*TANK,WINDSHIELD WASHER	Not Necessary	87.00 FL	*- FL
12	1		*SENSOR,W/SHLD WASHER TANK	Not Necessary	114.00 FL	*- FL
13	1		*EXTENSION,FR BUMPER	Cut	517.00 FL	*517.00 FL
14	1		*REINFORVEMENT,FR BUMPER	Dented	493.00 FL	*493.00 FL
15	1		*BAR,FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
16	1		*REINFORCEMENT,FR BMPR SIDE	Not Necessary	22.00 FL	*- FL
17	1		*REINF,FR BUMPER SIDE,LH	Not Necessary	60.00 FL	*- FL
18	1		*REINF,FR BUMPER SIDE,RH	Not Necessary	69.00 FL	*- FL
19	1		*GRILLE ASSY,RADIATOR	Broken	550.00 FL	*550.00 FL
20	1		*BODY KIT,OUTLANDER	Not Necessary	1,554.00 FN	*- FN
21	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
22	1		*FRONT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	5,868.00	3,224.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	969.22	725.42
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	310.80	0.00
Total Parts (\$\$)	4,587.98	2,498.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER PANEL,REINFORCEMENT & AFFECTED AREA	New	900.00	450.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	80.00
4	PERFORM RUST PREVENTION	New	40.00	0.00
5	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	REPLACE REINFORCEMENT FRONT BUMPER (Supplementary)	New	225.00	225.00
8	SPRAY PAINT REINFORCEMENT FRONT BUMPER (Supplementary)	New	175.00	175.00
Gross Labour Cost (\$\$)			1,960.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >