

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012557/EVF3E2

Date: 11/01/2022

REFERENCE

Insured/Claimant: TOH HONG KENG JAMES (ZHUO FENGQING JAMES)
Date of Loss: 12/12/2021

Policy No:
Nature of Claim: OD Claim No: 8338451140SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH4619T	Engine No:	4J11AB9066
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0600417
Reg. Date:	24/01/2019 (Man. Year: 2018)	Odometer:	53457 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$97,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,545.00	5,949.72	5,595.28	48.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	3,515.00	1,825.00	34.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,885.00	9,464.72	7,420.28	43.95
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	16,585.00	9,164.72	7,420.28	44.74
+ GST 7.00/7.00% (S\$)	1,160.95	641.53	519.42	44.74
Nett Amount (S\$)	17,745.95	9,806.25	7,939.70	44.74

INSPECTION

Date of Assignment: 13/12/2021

Date Inspected: 13/12/2021 Inspected At:

Estimated Period of Repair: 6.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, FR BUMPER	Dented	851.00 F	*851.00 FL
4	1		*GARNISH, FR BUMPER, LH	Not Necessary	48.00 F	*- FL
5	1		*EXTENSION, FR BUMPER	Cut	517.00 F	*517.00 FL
6	1		*BRACKET, FR BUMPER SIDE, LH	Not Necessary	18.00 F	*- FL
7	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 F	*- FL
8	1		*BRKT, FR BUMPER SIDE, LWR LH	Not Necessary	6.00 F	*- FL
9	1		*BRKT, FR BUMPER SIDE, LWR RH	Not Necessary	6.00 F	*- FL
10	1		*GARNISH, FR LICENSE PLATE	Cut	23.00 F	*23.00 FL
11	1		*GARNISH, FR BUMPER SIDE	Not Necessary	48.00 F	*- FL
12	1		*GARNISH, FR BUMPER SIDE	Not Necessary	48.00 F	*- FL
13	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 F	*220.00 FL
14	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 F	*220.00 FL
15	1		*GARNISH, FR BUMPER SIDE	Not Necessary	112.00 F	*- FL
16	1		*GARNISH, FR BUMPER SIDE	Not Necessary	112.00 F	*- FL
17	1		*COVER, FR BUMPER	Broken	361.00 F	*361.00 FL
18	1		*MOULDING, FR BUMPER, LH	Not Necessary	116.00 F	*- FL
19	1		*COVER, HEADLAMP SUPT PANEL	Crushed	50.00 F	*50.00 FL
20	1		*COVER, FR BUMPER	Not Necessary	25.00 F	*- FL
21	1		*GRILLE ASSY, RADIATOR	Broken	550.00 F	*550.00 FL
22	1		*BRACKET, RADIATOR GRILLE, RH	Not Necessary	17.00 F	*- FL
23	1		*BRACKET, RADIATOR GRILLE, LH	Not Necessary	13.00 F	*- FL
24	1		*REINFORCEMENT, FR BUMPER	Bent	493.00 F	*493.00 FL
25	1		*BAR, FR BUMPER GUARD	Not Necessary	130.00 F	*- FL
26	1		*REINFORCEMENT, FR BUMPER	Bent	135.00 F	*135.00 FL
27	1		*REINFORCEMENT, FR BMRP SIDE	Not Necessary	22.00 F	*- FL
28	1		*REINF, FR BUMPER SIDE, RH	Bent	69.00 F	*69.00 FL
29	1		*REINF, FR BUMPER SIDE, LH	Bent	60.00 F	*60.00 FL
30	1		*HOOD	Dented	980.00 F	*980.00 FL
31	1		*INSULATOR, HOOD	Not Necessary	133.00 F	*- FL
32	1		*WEATHERSTRIP, HOOD	Not Necessary	40.00 F	*- FL
33	1		*WEATHERSTRIP, HOOD	Not Necessary	41.00 F	*- FL
34	1		*LATCH, HOOD	Not Necessary	76.00 F	*- FL
35	1		*FENDER, FR LH	Dented	622.00 F	*622.00 FL
36	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	164.00 F	*- FL
37	1		*HEADLAMP ASSY, LH	Broken	1,948.00 F	*1,948.00 FL
38	1		*HEADLAMP ASSY, RH	Not Necessary	1,948.00 F	*- FL
39	1		*LAMP ASSY, FOG, FR LH	Not Necessary	350.00 F	*- FL
40	1		*LAMP ASSY, FOG, FR RH	Not Necessary	348.00 F	*- FL
41	1		*GARNISH, FR BUMPER, RH	Cut	48.00 F	*48.00 FL
42	1		*PANEL, HEADLAMP SUPPORT, UPR (Supplementary)	Bent	183.00 F	*183.00 FL
43	1		*MOULDING, FR WHEEL ARCH, LH (Supplementary)	Necessary	160.00 F	*160.00 FL
44	4		*TAPE, TAILGATE (Supplementary)	Necessary	16.00 F	*16.00 FL
45	2		*PLUG, BODY (Supplementary)	Necessary	6.00 F	*6.00 FL
46	8		*CLIPS (Supplementary)	Necessary	24.00 F	*24.00 FL
47	10		*CLIPS (Supplementary)	Necessary	20.00 F	*20.00 FL
48	10		*CLIPS (Supplementary)	Necessary	30.00 F	*30.00 FL
49	10		*RIVERTS (Supplementary)	Necessary	50.00 F	*50.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	11,545.00	7,706.00
					- List Item Discount on L Items 0.00/23.00% (\$)	0.00	1,756.28
					Total Parts (\$)	11,545.00	5,949.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW BONNET, FRT BUMPER, FRT FENDER LH, REPAIR FRT SUPPORT PANEL, FRT DOOR LH, FRT FENDER RH	New	2,250.00	1,125.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT DOOR LH, FRT SUPPORT PANEL	New	2,100.00	1,400.00
3	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
6	REPLACE FRONT BUMPER REINFORCEMENT (Supplementary)	New	450.00	450.00
7	RESPRAY FRONT BUMPER REINFORCEMENT (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			5,340.00	3,515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >