

ASS. REC. BY:

Stere

REF:

CS/AIG 21012557/EVF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X
N/S	O/S

Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SMH 4619T

Yr Regn: 2A/1/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Outlander cc 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 53457 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GF7W0600417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/50R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 12/12/21

D.O.I. 13/12/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-97K

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
TOH HONG KENG JAMES (ZHUO FENGQING JAMES) 15 WOODLANDS DRIVE 72 #14-41 SINGAPORE 738096 Contact No Mobile: 96252080	Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQING JAMES)
	Reg No/Reg Date	SMH4619T*CS3P/ 24/01/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600417
	Engine No	4J11AB9066
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	13/12/2021/ 11:30	BLC	442 / CocoLu	18623			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2250.00
RENEW BONNET, FRT BUMPER, FRT FENDER LH, REPAIR FRT SUPPORT PANEL					2.5	x	4.50	1125
FRT DOOR LH, FRT FENDER RH								2100.00
E PNT98000								1490
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH					4	x	359	50.00
FRT DOOR LH, FRT SUPPORT PANEL								30.00
M SUNDRY								120.00
FRT NUMBER PLATE WITH FRAME								40.00
A 54900099								20.00
CHECK WIRING & ELECTRICAL SYTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								
Sundry					1.00	851.00	00.00	851.00
M FACE,FR BUMPER					1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER,LH					1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER,RH					1.00	517.00	00.00	517.00
M EXTENSION,FR BUMPER					1.00	18.00	00.00	18.00
M BRACKET,FR BUMPER SIDE,LH					1.00	18.00	00.00	18.00
M BRACKET,FR BUMPER SIDE,RH					1.00	6.00	00.00	6.00
M BRKT,FR BUMPER SIDE,LWR LH					1.00	6.00	00.00	6.00
M BRKT,FR BUMPER SIDE,LWR RH					1.00	23.00	00.00	23.00
M GARNISH,FR LICENSE PLATE					1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE					1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE					1.00	220.00	00.00	220.00
M GARNISH,FR BUMPER SIDE					1.00	220.00	00.00	220.00
M GARNISH,FR BUMPER SIDE					1.00	112.00	00.00	112.00
M GARNISH,FR BUMPER SIDE					1.00	112.00	00.00	112.00
M GARNISH,FR BUMPER SIDE					1.00	361.00	00.00	361.00
M COVER,FR BUMPER					1.00	116.00	00.00	116.00
M MOULDING,FR BUMPER,LH								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
TOH HONG KENG JAMES (ZHUO FENGQING JAMES) 15 WOODLANDS DRIVE 72 #14-41 SINGAPORE 738096 Contact No Mobile: 96252080	Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQING JAMES)
	Reg No/Reg Date	SMH4619T*CS3P/ 24/01/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600417
	Engine No	4J11AB9066
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	13/12/2021/ 11:30	BLC	442 / CocoLu	18623			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER, HEADLAMP SUPT PANEL					1.00	50.00	00.00	50.00
M COVER, FR BUMPER					1.00	25.00	00.00	25.00
M GRILLE ASSY, RADIATOR					1.00	550.00	00.00	550.00
M BRACKET, RADIATOR GRILLE, RH					1.00	17.00	00.00	17.00
M BRACKET, RADIATOR GRILLE, LH					1.00	13.00	00.00	13.00
M REINFORCEMENT, FR BUMPER					1.00	493.00	00.00	493.00
M BAR, FR BUMPER GUARD					1.00	130.00	00.00	130.00
M REINFORCEMENT, FR BUMPER					1.00	135.00	00.00	135.00
M REINFORCEMENT, FR BMR SIDE					1.00	22.00	00.00	22.00
M REINF, FR BUMPER SIDE, RH					1.00	69.00	00.00	69.00
M REINF, FR BUMPER SIDE, LH					1.00	60.00	00.00	60.00
M HOOD					1.00	980.00	00.00	980.00
M INSULATOR, HOOD					1.00	133.00	00.00	133.00
M WEATHERSTRIP, HOOD					1.00	40.00	00.00	40.00
M WEATHERSTRIP, HOOD					1.00	41.00	00.00	41.00
M LATCH, HOOD					1.00	76.00	00.00	76.00
M FENDER, FR LH					1.00	622.00	00.00	622.00
M SHIELD, FR WHEELHOUSE, LH					1.00	164.00	00.00	164.00
M HEADLAMP ASSY, LH					1.00	1948.00	00.00	1948.00
M HEADLAMP ASSY, RH					1.00	1948.00	00.00	1948.00
M LAMP ASSY, FOG, FR LH					1.00	350.00	00.00	350.00
M LAMP ASSY, FOG, FR RH					1.00	348.00	00.00	348.00
LKK Auto Consultants hence notify the Repairer of the following:								
• To resurvey before/after spray painting								
• To display damaged part(s) during resurvey								
• Parts prices are subject to confirmation								
• Third party survey is on a "Without Prejudice" basis								
• No illegal modification(s) is allowed								
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company								
Acknolged by Repairer								
Authorized signatory and company stamp								
					Steve (LKK)			
					13/12/21, 12:00pm			
					OD-MML			
					Excess - ?			
					P/P			
					My B/L by			
					6 dgs			
Confirm & accepted by					7% GST on			
					15596.00			
					Total Payable			
					15,596.00			
					1091.72			
					16,687.72			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.