



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 12.12.2021
Emailed : 28.12.2021, 2.35pm
Date survey : 13.12.2021

VEHICLE NO : SMH 4619 T
MODEL : MIT OUTLANDER 2.0
WIP : 18623

Material	:	\$	5,879.72
Labour	:	\$	3,585.00
Sub-Total	:	\$	9,464.72
	:		-
Less Excess	:	\$	300.00
Total	:	\$	9,164.72
GST 7%	:	\$	641.53
Grand Total	:	\$	9,806.25
Finalise By/Date	:	LOI / 28/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK _____ WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/12/2021	Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQ)
	Reg No/Reg Date	SMH4619T*CS3P/ 24/01/2019
	Date In/Mileage	13/12/2021/ 45808
	Chassis/Package	GF7W0600417 /#
	Engine No	4J11AB9066
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/12/2021/ 11:02	BLK	260 / AiTing	18623			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE BONNET, FRONT BUMPER, LH FRONT FENDER, REPAIR FRONT SUPPORT PANEL, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								1125.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, LH FRONT FENDER, LH FRONT DOOR, FRONT SUPPORT PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME								1400.00
A 54900099 CHECK WIRING & ELECTRICAL SYTEM								30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK MUT TESTER AND CLEAR TROUBLE CODE								120.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS								40.00
M SUNDRY SUNDRIES								20.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								50.00
E PNT88000 REPLACE FRONT BUMPER REINFORCEMENT → Supp								450.00
E PNT98000 RESPRAY FRONT BUMPER REINFORCEMENT → Supp								350.00
X EXC EXCESS								-300.00
X	FACE,FR BUMPER				1.00	851.00	23.00	655.27
X	GARNISH,FR BUMPER,RH				1.00	48.00	23.00	36.96
X	EXTENSION,FR BUMPER				1.00	517.00	23.00	398.09
X	GARNISH,FR LICENSE PLATE				1.00	23.00	23.00	17.71
X	GARNISH,FR BUMPER SIDE				1.00	220.00	23.00	169.40
X	GARNISH,FR BUMPER SIDE				1.00	220.00	23.00	169.40
X	COVER,FR BUMPER				1.00	361.00	23.00	277.97
X	COVER,HEADLAMP SUPT PANEL				1.00	50.00	23.00	38.50
X	GRILLE ASSY,RADIATOR				1.00	550.00	23.00	423.50
X	REINFORCEMENT,FR BUMPER				1.00	493.00	23.00	379.61

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/12/2021	<table> <tr> <td>Cust No/Name</td><td>/TOH HONG KENG JAMES (ZHUO FENGQ)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMH4619T*CS3P/ 24/01/2019</td></tr> <tr> <td>Date In/Mileage</td><td>13/12/2021/ 45808</td></tr> <tr> <td>Chassis/Package</td><td>GF7W0600417 /#</td></tr> <tr> <td>Engine No</td><td>4J11AB9066</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 MODERN(995)</td></tr> <tr> <td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr> </table>	Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQ)	Reg No/Reg Date	SMH4619T*CS3P/ 24/01/2019	Date In/Mileage	13/12/2021/ 45808	Chassis/Package	GF7W0600417 /#	Engine No	4J11AB9066	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK
Cust No/Name	/TOH HONG KENG JAMES (ZHUO FENGQ)														
Reg No/Reg Date	SMH4619T*CS3P/ 24/01/2019														
Date In/Mileage	13/12/2021/ 45808														
Chassis/Package	GF7W0600417 /#														
Engine No	4J11AB9066														
Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)														
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 11:02	BLK	260 / AiTing	18623

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REINFORCEMENT,FR BUMPER	1.00	135.00	23.00	103.95
X REINF,FR BUMPER SIDE,RH	1.00	69.00	23.00	53.13
X REINF,FR BUMPER SIDE,LH	1.00	60.00	23.00	46.20
X HOOD	1.00	980.00	23.00	754.60
X FENDER,FR LH	1.00	622.00	23.00	478.94
X HEADLAMP ASSY,LH	1.00	1948.00	23.00	1499.96
X PANEL,HEADLAMP SUPPORT,UPR	1.00	183.00	23.00	140.91
X MOULDING,FR WHEEL ARCH,LH	1.00	160.00	23.00	123.20
X TAPE,TAILGATE	4.00	4.00	23.00	12.32
X PLUG,BODY	2.00	3.00	23.00	4.62
X CLIP,HOOD INSULATOR	8.00	3.00	23.00	18.48
X CLIP,ENG ROOM COVER	10.00	2.00	23.00	15.40
X CLIP,RR BUMPER	10.00	3.00	23.00	23.10
X RIVET,FR BUMPER	10.00	5.00	23.00	38.50

Z TEXT

AIG OD CLAIM
 DOA : 12.12.21
 SURVEYOR STEVE LKK 13.12.21
 POLICY NO : 1900008037-01 REPAIR 06 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,879.72	Nett	9,164.72
Labour	3,475.00	7% GST on	641.53
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	9,806.25
Diagnostics Job	0.00		
Sundry/Others	-240.00		
Total(w/o GST)	9,164.72		

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMH 4619 T

<u>Materials</u>		<u>Cost (\$)</u>
1	Panel, headlamp support, upr / BT	183.00
2	Moulding, Fr wheel arch, LH / nec	160.00
3	Tape, tailgate (x4) / nec	16.00
4	Plug, body (x2) / nec	6.00
5	Clips (x8) / nec	24.00
6	Clips (x10) / nec	20.00
7	Clips (x10) / nec	30.00
8	Rivets (x10) / nec	50.00

Total 489.00

Less 23% 112.47

Total Materials 376.53

<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front bumper reinforcement	450.00 /
2	Respray front bumper reinforcement	350.00 /

Total Labour 800.00

Taxable Amount 1,176.53

7% GST 82.36

Grand total 1,258.89

Thank You.

Yours faithfully,
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SWT 4619TWIP: 18623 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Headlamp Support UPR	? / SUPP		✓ DD	
2	Reinforcement Front Bumper UPR	? / SUPP		✓ DD	
3	Reinforcement Front Bumper LWR	? / SUPP		✓ DD	
4	Reinforcement Front Bumper LH	? / SUPP		✓ DD	
5	Reinforcement Front Bumper RH	? / SUPP		✓ DD	
6	Moulding Front Wheel Arch	? / SUPP		✓ PK	
7	Plug Front Hood	? / SUPP		✓ PK	
8	Clip Hood Insulator	? / SUPP		✓ PK	
9	Clip Front Bumper	? / SUPP		✓ PK	See
10	Clip Grille Radiator	? / SUPP		✓ PK	15/12/21
11	Rivet Front Bumper	? / SUPP		✓ PK	
12	Replace Reinforcement Front Bumper	? / SUPP	\$450	✓	
13	Respray Reinforcement Front Bumper	? / SUPP	\$450 350	✓	
14		? / SUPP			
15	Additional 1 Repair Day	? / SUPP		✓	
16	≤ 7 days	? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: antanderSURVEYOR: Steve

SMV 46197

After erase all DTC

All DTCs

2021.12.27

Setting	
Item	Information
M.U.T.-3 Version	SEW21121-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2019MY

All DTCs

2021.12.27

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition			
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs				
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs				
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs				
	AUTO CRUISE	GAS_0E640000		Non-target System				
	4WS/Electric Power Steering	EPS_45880040		No DTCs				
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs				
	SRS-AIR BAG	ORC_81047302		No DTCs				
	Air Conditioner	AC_80080011		No DTCs				
	ETACS	ETACS_83040801		No DTCs				
	Meter	MTR_84084001		No DTCs				
	Steering Angle Sensor	GS_SAS_47000100		Non-target System				
	AND	AND_8C080002		Non-equipped System or Communication Error				
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error				
	LIN	ETACS_83040801		Non-target System				
	Power Gate	ETG_92080000		Non-equipped System or Communication Error				

All DTCs

2021.12.27

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	KOS/IMMO/Keyless	KOS_8A880020		No DTCs		
	OSS	OSS_9588000B		No DTCs		
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
	ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
	Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
	EPB	EPB_4C080000		No DTCs		
	Gateway	GW_C1000000		Non-equipped System or Communication Error		
	FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		