

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI21012564/T1QF3N2**Date:** 07/01/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000071
<b>Claimant Vehicle No :</b>	SHA2096K	<b>Insured Vehicle No :</b>	SLR9528Z
Date of Loss:	10/12/2021	Nature of Claim:	TP Claim No: M2105734

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA2096K</b>	Engine No:	D4FDGU690474
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU096557
Reg. Date:	24/11/2016 (Man. Year: 2016)	Odometer:	516238 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,865.08	3,358.52	506.56	13.11
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	960.00	560.00	400.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,836.08</b>	<b>3,929.52</b>	<b>906.56</b>	<b>18.75</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,150.00</b>		
<b>(S\$)</b>	4,836.08	3,150.00	1,686.08	34.86
<b>+ GST 7.00/7.00% (S\$)</b>	338.53	220.50	118.03	34.87
<b>Nett Amount (S\$)</b>	<b>5,174.61</b>	<b>3,370.50</b>	<b>1,804.11</b>	<b>34.86</b>

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	13/12/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2022)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA2096K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	-	*1,052.20 FL
2	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*FRT BUMPER GRILLE LH	Deformed	187.20 FL	-	*187.20 FL
4	1		*FRT BUMPER BRACKET TOP LH	Not Necessary	44.80 FL	-	*- FL
5	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	-	*1,480.00 FL
6	1		*HEADLAMP LH	Cut	1,388.00 FL	-	*1,388.00 FL
7	1		*FRT BUMPER REINFORCEMENT	Not Necessary	588.40 FL	-	*- FL
8	1		*FRT NUMBER PLATE WITH TRIM COVER	Cracked	55.00 F	-	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,817.60</b>	<b>4,184.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	952.52	825.88
<b>Total Parts (\$\$)</b>	<b>3,865.08</b>	<b>3,358.52</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHK ALL LIGHTING	New	60.00	30.00
Gross Labour Cost (\$\$)			960.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >