

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012565/BYA3Q2
Date: 19/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJP991L	Insured Vehicle No :	SLW1250A
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	2016042625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP991L	Engine No:	L15A5207717
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11306347
Reg. Date:	11/03/2009 (Man. Year: 2008)	Odometer:	200681 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dayton 3 mm	Rear Left Side:	Good Rich 3 mm
Front Right Side:	Dayton 3 mm	Rear Right Side:	Good Rich 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,250.04	2,933.08	6,316.96	68.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,630.00	2,390.00	59.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,270.04	4,563.08	8,706.96	65.61
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	13,270.04	2,500.00	10,770.04	81.16
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,807.45		

INSPECTION

Date of Assignment:	13/12/2021		Accident Assist SG (HQ)
Date Inspected:	14/12/2021	Inspected At:	24 Sin Ming Lane, #01-94 Mid View City Singapore 573970
Estimated Period of Repair:	5.0 days		

Adjuster: Lim Teow Guan**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	956.00 FL	*956.00 FL
2	1		*REAR BUMPER SIDE RETAINER N/S	Necessary	91.00 FL	*62.40 FL
3	1		*TAILLAMP N/S	Cut	530.00 FL	*335.00 FL
4	1		*REAR SIDE BODY PANEL (N/S FENDER)	Dented	1,250.00 FL	*1,125.00 FL
5	1		*REAR SIDE BODY INNER PANEL O/S	Not Damaged	1,305.30 FL	*- FL
6	1		*REAR SIDE BODY PANEL GLASS MOULDING O/S	Not Damaged	135.00 FL	*- FL
7	1		*REAR SIDE BODY PANEL EMBLEM (AIRWAVE) O/S	Not Necessary	85.30 FL	*- FL
8	1		*REAR SIDE BODY PANEL INNER TRIM O/S	Not Damaged	344.90 FL	*- FL
9	1		*REAR SIDE BODY PANEL INNER SHIELD O/S	Not Damaged	163.50 FL	*- FL
10	1		*REAR DOOR N/S	Dented	1,161.30 FL	*987.00 FL
11	1		*REAR DOOR WEATHERSTRIP O/S	Not Damaged	115.80 FL	*- FL
12	1		*REAR DOOR INNER LOCK O/S	Not Damaged	290.00 FL	*- FL
13	2		*REAR DOOR HINGE	Not Damaged	96.80 FL	*- FL
14	1		*REAR DOOR CHECKER O/S	Not Damaged	65.00 FL	*- FL
15	2		*REAR DOOR OUTER HANDLE O/S	Not Damaged	130.30 FL	*- FL
16	1		*REAR DOOR INNER TRIM O/S	Not Damaged	451.60 FL	*- FL
17	1		*REAR DOOR INNER SEAL O/S	Not Damaged	75.00 FL	*- FL
18	1		*REAR DOOR GLASS REGULATOR ASSY O/S	Not Damaged	471.80 FL	*- FL
19	1		*REAR DOOR GLASS RUN CHANNEL O/S	Not Damaged	103.65 FL	*- FL
20	1		*REAR DOOR BLACK TAPE N/S	Necessary	60.00 FL	*32.20 FL
21	1		*REAR AXLE	Not Damaged	1,406.80 FL	*- FL
22	1		*REAR WHEEL HUB O/S	Not Damaged	364.00 FL	*- FL
23	1		*REAR WHEEL HUB BEARING O/S	Not Damaged	122.00 FL	*- FL
24	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
25	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*SET TAILLAMP CLIPS N/S	Necessary	25.00 FS	*25.00 FS
27	1		*TAILLAMP SEAL N/S	Necessary	30.00 FS	*20.00 FS
28	1		*REAR SIDE BODY PANEL SEALANT N/S FENDER	Necessary	100.00 FS	*30.00 FS
29	1		*REAR SIDE BODY INNER PANEL O/S	Not Necessary	100.00 FS	*- FS
30	1		*SET REAR SIDE BODY PANEL INNER TRIM CLIPS O/S	Not Necessary	80.00 FS	*- FS
31	1		*SET REAR SIDE BODY PANEL INNER SHIELD CLIPS O/S	Not Necessary	60.00 FS	*- FS
32	1		*REAR DOOR SEALANT	Necessary	70.00 FS	*30.00 FS
33	1		*REAR DOOR INNER TRIM CLIPS O/S	Not Necessary	80.00 FS	*- FS
34	1		*REAR ALLOY RIM R15 O/S	Not Damaged	480.00 FS	*- FS
35	1		*REAR TYRE R15 O/S	Not Damaged	220.00 FS	*- FS
36	1		*BRAKE FLUID	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,205.05	3,632.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,955.01	699.52
Total Parts (\$)	9,250.04	2,933.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA }	New	1,500.00	1,000.00
2	TO REMOVE /REPLACE DAMAGED PARTS & COMPONENTS }	New	800.00	0.00
3	TO APPLY UNDERCOATING FOR RUST ROOFING	New	100.00	0.00
4	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	100.00	30.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
6	SPRAY PAINTING ON ACCIDENT AREA	New	1,400.00	600.00
Gross Labour Cost (S\$)			4,020.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >