

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921
 Email: ryderautoworkshop@gmail.com
 Tel: 67418277 Fax: 67468277

* - some parts prices need verification

RS

ESTIMATE OF REPAIR

Veh# : YP4528M
Accident Date 11/12/2021

Model: ISUZU NNR85
12/10/2017

Location BARTLEY ROAD EAST

3p: YP3171P (China Taiping)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front n/s head lamp	1,324.40		
2	2 pcs	Front n/s head lamp clips		140 24.00	
3	1 pc	Front n/s signal lamp	546.60		
4	2 pcs	Front n/s signal lamp clips		140 24.00	
5	1 pc	Front n/s A pillar	2,130.50		
6	1 pc	Front n/s door pillar garnish	696.20		
7	6pcs	Front n/s door pillar garnish clips	72.00		
8	1 pc	Front n/s door pillar garnish weather strip	120.00		
9	1 pc	Front n/s wing mirror (square)	268.10		
10	1 pc	Front n/s wing mirror (round)	120.50		
11	1 pc	Front n/s wing mirror bracket	506.70		
12	1 pc	Front n/s wing mirror bracket garnish	96.70		
13	1 set	Front windscreen moulding	602.40		
14	1 pc	Front n/s door	4,886.20		
15	1 pc	Front n/s door garnish strip (middle)	322.40		
16	1 pc	Front n/s door weatherstrip	506.2		
17	1 pc	Front n/s door window seal (outer)	202.2		
18	1 pc	Front n/s door window frame seal (outer)	213.5		
19	2 pcs	Front n/s door hinges (upper & lower)	607.2		
20	1 pc	Front n/s door window regulator	709.2		
21	1 pc	Front n/s door window motor	676.20		
22	1 pc	Front n/s door lock	360.20		
23	1 pc	Front n/s door lock striker	147.2		
24	2pcs	Front n/s door hinges	300		
25	1 pc	Front n/s door lock handle (outer)	460.20		
26	1 pc	Front n/s B pillar	2,430.50		
27	1 pc	Front n/s step fabric	211.70		
28	1 pc	Front n/s step fabric bracket	398.80		
29	1 pc	Front n/s wheel arch panel			
30	1 pc	Front n/s wheel arch step garnish (inner)			
31	1 pc	Rear n/s panel frame		200.00	
		Sub Total:	18,915.80	248.00	0.00
			15%	0%	0%
		After Less %:	16078.43	248.00	0.00
		Labour			
1		To dismantle, straighten & welding.		1,600.00	
2		To spray painting.		800.00	
3		To remove and refit front n/s door		140.00	
		To remove & refit instrument panel, roof lining, seat & floor mats to facilitate repair		280.00	
		To check wiring.		120.00	
		To re seal anti rust.		150.00	
		Sub Total:		3,090.00	
		Total:		19,416.43	
		After Less 20%:		15,533.14	

7. /scr ~~710~~ 710
 encl
 nec
 - encl mis
 - nec
 X ~~710~~ r
 /DT ~~710~~ 300
 - nec 40
 - ~~710~~ S
 - ~~710~~ era
 - mis
 - ~~710~~ mis 210
 - ~~710~~ mis
 XNW
 - DT ~~710~~ 1200
 - scr
 7. /cut 150
 - DM ~~710~~
 - DJ S
 Per X repeat
 1. XSUC
 1. XSUC
 1. XSUC
 1. XSUC
 1. ~~XSUC~~ ~~710~~ ~~710~~ /DIS ~~710~~ 200
 - SLV 200
 /DT 1845
 XSUC
 XSUC
 7. X
 7. X
 Xr

~~600~~ 800 ~~100~~
 800 800
 50
 100
 30
 30


Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Thru an @lhauto. loan

82235769

15/12/21 1700

L/S 5 days w/



AL 8778 1999
24 hr accident call



YP4528M ESTIMATEPg1

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : YP4528M

Model:

ISUZI NNR85

12/10/2017

Accident Date 11/12/2021

Location BARTLEY ROAD EAST

3P: YP3171P (China Taiping)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front n/s door signal lamp	285.20		
2	1 pc	Front n/s wheel arch	310.00		
3	1 pc	Front n/s wheel arch seal inner	75.00		
4	1 pc	Front n/s door instruction sticker		200.00	
5	1 pc	n/s air vent	90.00		
6	4pcs	Front n/s panel clips		40.00	
Sub Total:			760.20	240.00	0.00
			15%	0%	0%
After Less %:			646.17	240.00	0.00
Total:			886.17		
After Less 20%:			708.94		

scr 92
/scr 180
/DIS
100
scr 30
200/11pc

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

F: 6600

6600

6650



8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: