

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012572/UTY3N2**Date:** 20/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00133972102

Claimant Vehicle No : GBH162A**Insured Vehicle No :** SLF477J

Date of Loss: 30/09/2021

Nature of Claim: TP

Claim No: SNM21D205600/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH162A**

Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)

Engine No: ZD30026667N

Reg. Date: 27/12/2017 (Man. Year: 2017)

Chassis No: JN1SC2F24Z0861024

Colour: White

Odometer: 201595 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|----------------|
| Front Tyre Size: | 195R15 | Rear Tyre Size: | 155R13(D) |
| Front Left Side: | Falken 6 mm | Rear Left Side: | Sailwin 6/6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Sailwin 6/6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 964.61 | 633.99 | 330.62 | 34.27 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,015.00 | 720.00 | 295.00 | 29.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 1,979.61 | 1,353.99 | 625.62 | 31.60 |
| Approved Total (Overridden) (S\$) | | 1,050.00 | | |
| (S\$) | 1,979.61 | 1,050.00 | 929.61 | 46.96 |
| + GST 7.00/7.00% (S\$) | 138.57 | 73.50 | 65.07 | 46.96 |
| Nett Amount (S\$) | 2,118.18 | 1,123.50 | 994.68 | 46.96 |

INSPECTION

Date of Assignment: 13/12/2021

Date Inspected: 13/12/2021 Inspected At:

ETHOZ Protect Pte Ltd (Tampines)
22 Tampines St 92
Singapore 528876

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | (Last Synchronised: 20 Dec 2021) | |
| Parts: | N/A | NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBH162A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|------------|------------|
| 1 | 1 | | *CENTRE DROP PANEL/TAILGATE (NPA) | Repair | 0.00 FL | *- FL |
| 2 | 1 | | *END PANEL (NPA) | Repair | 0.00 FL | *- FL |
| 3 | 1 | | *REAR RH DROP PANEL BRACKET | Bent | 195.63 FL | *195.63 FL |
| 4 | 1 | | *REAR RH DROP PANEL BRACKET LOCK | Serviceable | 48.75 FL | *- FL |
| 5 | 2 | | *DROP PANEL RUBBER STOPPER | Cut | 50.00 FS | *50.00 FS |
| 6 | 1 | | *70KM/H STICKER | Not Necessary | 20.00 FS | *- FS |
| 7 | 1 | | *13 PAX STICKER | Not Necessary | 20.00 FS | *- FS |
| 8 | 1 | | *ADVERTISEMENT STICKER-DROP PANEL | Not Necessary | 180.00 FS | *- FS |
| 9 | 1 | | *REAR NUMBER PLATE | Bent | 35.00 FS | *20.00 FS |
| 10 | 1 | | *SET REAR REVERSE SENSOR | Damaged | 200.00 FS | *200.00 FS |
| 11 | 1 | | *TAIL LAMP ASSY (RH) | Cracked | 266.30 FL | *208.80 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|---------------|
| Sub Total (\$\$) | 1,015.68 | 674.43 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 51.07 | 40.44 |

| | | |
|---------------------------|---------------|---------------|
| Total Parts (\$\$) | 964.61 | 633.99 |
|---------------------------|---------------|---------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | LABOUR TO FACILITATE REPAIR | New | 400.00 | 400.00 |
| 2 | TO SPRAY PAINT ON AFFECTED AREAS | New | 500.00 | 300.00 |
| 3 | SPRAY RUST PROOF ON AFFECTED AREA | New | 80.00 | 0.00 |
| 4 | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | New | 35.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 1,015.00 | 720.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >