

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012573/TGA3Q2**Date:** 14/06/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210002864
Claimant Vehicle No :	GBD7434R	Insured Vehicle No :	SJG5115P
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	0093347718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD7434R	Engine No:	263A20005501728
Make & Model:	FIAT DOBLO, 1.3 D SX Cargo (M)	Chassis No:	ZFA26300006186070
Reg. Date:	24/04/2015 (Man. Year: 2014)	Odometer:	128638 km
Colour:	White		
Engine Capacity:	1248 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,066.33	6,350.27	1,716.06	21.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,840.00	1,150.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,056.33	8,190.27	2,866.06	25.92
Approved Total (Overridden) (S\$)		6,550.00		
Nett Amount (S\$)	11,056.33	6,550.00	4,506.33	40.76
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,857.45		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment:	13/12/2021	Sin Yu Sin Workshop (HQ)
Date Inspected:	13/12/2021 Inspected At:	1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE LH	Bent	1,525.30 FL	*1,525.30 FL
2	1		*REAR TAILGATE 90 MULTJIET EMBLEM LH	Necessary	108.60 FL	*108.60 FL
3	1		*REAR TAILGATE MECHANISM LOCK LH	Not Necessary	290.50 FL	*- FL
4	1		*REAR TAILGATE INNER BOARD LH	Cracked	310.60 FL	*297.20 FL
5	1		*REAR TAILGATE RH	Bent	1,874.50 FL	*1,420.40 FL
6	1		*REAR TAILGATE UPPER MECHANISM LOCK RH	Not Necessary	290.50 FL	*- FL
7	1		*REAR TAILGATE UPPER LOCK STRIKER RH	Not Necessary	65.00 FL	*- FL
8	1		*REAR TAILGATE LOCK STRIKER (CENTER)RH	Not Necessary	65.00 FL	*- FL
9	1		*REAR TAILGATE LOWER MECHANISM LOCK RH	Bent	290.50 FL	*240.37 FL
10	1		*REAR TAILGATE LOWER LOCK STRIKER RH	Not Necessary	65.00 FL	*- FL
11	1		*REAR TAILGATE WEATHERSTRIP (CENTRE)RH	Cut	148.50 FL	*148.50 FL
12	1		*REAR WEATHERSTRIP	Cut	410.60 FL	*410.60 FL
13	1		*REAR BUMPER	Deformed	797.80 FL	*627.00 FL
14	2		*REAR BUMPER SIDE RETAINER L/R	Deformed	137.80 FL	*137.80 FL
15	2		*REAR BUMPER REFLECTOR LAMP L/R	Cut	197.20 FL	*197.20 FL
16	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	475.30 FL	*475.30 FL
17	1		*REAR BUMPER TOWING COVER	Deformed	67.00 FL	*67.00 FL
18	1		*REAR BUMPER OUTER PROTECTOR	Deformed	310.80 FL	*310.80 FL
19	1		*REAR END PANEL	Bent	430.80 FL	*332.94 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	187.60 FL	*187.60 FL
21	1		*REAR TAILGATE DOBLO EMBLEM RH	Necessary	124.80 FL	*124.80 FL
22	1		*REAR TAILGATE WINDSCREEN SEALANT LH	Necessary	80.00 FS	*40.00 FS
23	1		*REAR TAILGATE 70KM/H STICKER LH	Necessary	20.00 FS	*20.00 FS
24	1		*REAR TAILGATE INNER BOARD CLIP	Necessary	30.00 FS	*20.00 FS
25	1		*REAR TAILGATE WINDSCREEN SEALANT RH	Necessary	80.00 FS	*40.00 FS
26	1		*REAR TAILGATE 6 PAX STICKER RH	Necessary	20.00 FS	*20.00 FS
27	1		*REAR TAILGATE INNER BOARD CLIP RH	Necessary	30.00 FS	*20.00 FS
28	1		*REAR REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
29	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
30	1		*REAR END PANEL GARNISH CLIP	Necessary	20.00 FS	*10.00 FS
31	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,883.70	7,011.41
- List Item Discount on L Items 10.00/10.00% (\$\$)	817.37	661.14
Total Parts (\$\$)	8,066.33	6,350.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO TRANSFER REAR TAILGATE COMPONENT PARTS TO NEW REAR TAILGATE LH	New	100.00	60.00
3	TO TRANSFER REAR TAILGATE COMPONENT PARTS TO NEW REAR TAILGATE RH	New	100.00	60.00
4	TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS LH	New	120.00	60.00
5	TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS RH	New	120.00	40.00
6	TO REMOVE,REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	30.00
7	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS ,GARNISH SEAT ,ETC FOR NECESSARY REPAIRS	New	150.00	60.00
8	TO STRAIGHTEN REPAIR ,REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,100.00	700.00
9	TO SPRAY PAINTING ON AFFECTED AREA	New	1,100.00	800.00
			Gross Labour Cost (\$)	2,990.00
				1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >