

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012576/UQY3N2**Date:** 14/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00060052100

Claimant Vehicle No : SMM7147S **Insured Vehicle No :** SKS3250U

Date of Loss: 08/12/2021 Nature of Claim: TP Claim No: SNM21D207146/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM7147S**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR5372627

Reg. Date: 11/07/2019 (Man. Year: 2019) Chassis No: MR2B23F3901181768

Colour: Black Odometer: 26416 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,959.05	970.85	2,988.20	75.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,250.00	850.00	40.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,059.05	2,220.85	3,838.20	63.35
+ GST 7.00/7.00% (\$\$)	424.13	155.46	268.67	63.35
Nett Amount (\$\$)	6,483.18	2,376.31	4,106.87	63.35

INSPECTION

Date of Assignment: 13/12/2021

Date Inspected: 17/12/2021 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM7147S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	793.20 FL	*- FL
2	1		*BOOTLID HINGE RH	Not Necessary	65.80 FL	*- FL
3	1		*BOOTLID HINGE LH	Not Necessary	65.80 FL	*- FL
4	1		*BOOTLID EMBLEM	Not Necessary	50.70 FL	*- FL
5	1		*BOOTLID LOGO-VIOS	Necessary	45.60 FL	*45.60 FL
6	1		*BOOTLID LOGO-E	Necessary	35.50 FL	*35.50 FL
7	1		*END PANEL	Repair	742.70 FL	*- FL
8	1		*REAR BUMPER	Torn	521.00 FL	*521.00 FL
9	1		*REAR BUMPER RETAINER RH	Not Necessary	154.80 FL	*- FL
10	1		*REAR BUMPER RETAINER LH	Not Necessary	154.80 FL	*- FL
11	4		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	332.70 FL	*332.70 FL
13	1		*REAR BUMPER REFLECTOR RH	Not Necessary	907.50 FL	*- FL
14	1		*REAR BUMPER REFLECTOR LH	Not Necessary	907.50 FL	*- FL
15	1		*REAR FENDER INNER SHIELD LH	Not Necessary	34.80 FL	*- FL
16	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FS	*- FS
18	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*BOOT ANTENNA SENSOR	Cracked	71.00 FL	*71.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,185.40	1,227.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,226.35	256.95
Total Parts (S\$)	3,959.05	970.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	600.00
3	ANTI-RUST COATING	New	150.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			2,100.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >