

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012577/TEA3Q2**Date:** 16/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501986-04
Claimant Vehicle No :	SH9271H	Insured Vehicle No :	SKN660R
Date of Loss:	11/12/2021	Nature of Claim:	TP
		Claim No:	3500114688SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9271H	Engine No:	2ZRR970370
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU703538904
Reg. Date:	23/12/2016 (Man. Year: 2016)	Odometer:	589352 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,687.92	479.67	3,208.25	86.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,525.00	315.00	17.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,527.92	2,004.67	3,523.25	63.74
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	5,527.92	1,600.00	3,927.92	71.06
+ GST 7.00/7.00% (S\$)	386.95	112.00	274.95	71.06
Nett Amount (S\$)	5,914.87	1,712.00	4,202.87	71.06
+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
+ Car Rental (3.5 x S\$125.40/day) (S\$)		438.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,327.90		

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	13/12/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER EMBLEM	Necessary	86.50 FL	*86.50 FL
2	1		*FRONT LH DOOR WING MIRROR ASSY	Not Necessary	1,728.70 FL	*- FL
3	1		*FRONT LH DOOR PANEL	Repair	1,264.00 FL	*- FL
4	1		*REAR LH DOOR PANEL	Repair	1,258.30 FL	*- FL
5	1		*FRONT WHEEL COVER	Cut	346.40 FL	*346.40 FL
6	1		*FRONT DOOR COMFORT STICKER	Necessary	75.00 FS	*75.00 FS
7	1		*REAR FUEL PETROL STICKER	Not Necessary	20.00 FS	*- FS
8	1		*REAR DOOR COMFORT APP	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,858.90	587.90
- List Item Discount on L Items 25.00/25.00% (\$)	1,170.98	108.23
Total Parts (\$)	3,687.92	479.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	650.00	525.00
2	SPRAY PAINTING CHARGE	New	1,100.00	1,000.00
3	REMOVE/REFIX DOOR PARTS	New	90.00	0.00
			Gross Labour Cost (S\$)	1,840.00
				1,525.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >