



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE  
HQ TRANSPORT COMMAND  
KRANJI CAMP 3  
151 CHOA CHU KANG WAYSINGAPORE 688248

Ref: CC2/MIDA21012580/Rpq2

Date: 20/01/2022

Code: MIDA

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	MID 22023	<b>Veh. Inspected</b>	SJP 6441T
<b>Policy No.</b>	OA21028859	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CY 20/21/0050	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	13/12/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	mitsubishi LANCER 1.6 A	<b>c.c</b>	1584
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	JMYSTCS3A9U005388	<b>Colour</b>	GREY
<b>Odometer</b>	150247 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/60 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	195/60 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	195/60 R15	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	195/60 R15	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/12/2021	<b>Inspection Date</b>	27/12/2021
<b>Survey held at</b>	48 TOH GUAN RD EAST #02-146/147		
<b>Repairer</b>	AUTOMOTIVE REPAIR CENTRE PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 6441T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CRACKED	680.00	680.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	50.00	-
1	REAR FENDER RH	BUCKLED	700.00	700.00
1	REAR FENDER SHIELD RH	NOT NECESSARY	82.00	-
10	REAR FENDER SHIELD CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR DOOR LH	BENT	580.00	580.00
1	REAR DOOR HANDLE ASSY RH	CRACKED	95.00	95.00
1	TAIL LAMP RH	SCRATCHED	490.00	490.00
	LESS 10% DISCOUNT		-	-264.50
			<b>2,777.00</b>	<b>2,380.50</b>
<b><u>LABOUR</u></b>				
	SPRAY PAINT (REAR BUMPER ,REAR FENDER RH & REAR DOOR RH).		700.00	600.00
	REMOVE AND REFIT ACCIDENT AFFECTED AREA.		800.00	400.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR .		150.00	60.00
	REAR FENDER RH ,INCLUDE FITTINGS ,CUTTING ,WELDING & RE-ALIGN.		600.00	400.00
	COMPUTERIZED REAR WHEEL ALIGNMENT RH.	NOT NECESSARY	100.00	-
	APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL.		100.00	80.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		50.00	30.00
			<b>2,500.00</b>	<b>1,570.00</b>
<b>GRAND TOTAL</b>			<b>5,277.00</b>	<b>3,950.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,150.00</b>

Report Ref No. CC2/MIDA21012580/Rpq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SJP 6441T

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SJP 6441T

## RE-INSPECTION

