

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21012581/KES3Q2**Date:** 13/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SLH417Y	<b>Insured Vehicle No :</b>	SLS2512J
Date of Loss:	12/12/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLH417Y</b>	Engine No:	2ZRR961679
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU103537280
Reg. Date:	21/10/2016 (Man. Year: 2016)	Odometer:	249878 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Tourador 7 mm	Rear Left Side:	Tourador 7 mm
Front Right Side:	Tourador 7 mm	Rear Right Side:	Tourador 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,611.00	2,587.57	4,023.43	60.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,320.00	1,280.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,211.00</b>	<b>3,907.57</b>	<b>5,303.43</b>	<b>57.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	9,211.00	3,100.00	6,111.00	66.34
<b>+ GST 7.00/7.00% (S\$)</b>	644.77	217.00	427.77	66.34
<b>Nett Amount (S\$)</b>	<b>9,855.77</b>	<b>3,317.00</b>	<b>6,538.77</b>	<b>66.34</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,724.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,720.00</b>		

INSPECTION

Date of Assignment:	13/12/2021		
Date Inspected:	14/12/2021	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2022)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH417Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	929.00 FL	*- FL
2	1		*REAR TAILGATE OUTER GARNISH COVER	Cracked	891.00 FL	*891.00 FL
3	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.00 FL	*54.60 FL
4	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	75.00 FL	*54.60 FL
5	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	65.00 FL	*47.90 FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	251.00 FL	*- FL
7	1		*REAR TAILGATE INNER LOCK	Repair	452.00 FL	*- FL
8	1		*REAR TAILGATE WEATHERSTRIPE	Serviceable	360.00 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Not Necessary	75.00 FL	*- FL
10	1		*REAR BUMPER	Buckled	448.00 FL	*448.00 FL
11	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	112.00 FL	*- FL
12	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	112.00 FL	*- FL
13	1		*REAR BUMPER LOWER GARNISH COVER	Dented / Cut	486.00 FL	*486.00 FL
14	1		*REAR BUMPER TOWING COVER	Dented	25.00 FL	*25.00 FL
15	1		*REAR BUMPER ANTENNA SENSOR	Cracked	75.00 FL	*75.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	337.00 FL	*337.00 FL
17	1		*REAR UPPER TAIL LAMP LH	Serviceable	433.00 FL	*- FL
18	1		*REAR LOWER TAIL LAMP LH	Mtg Cracked	486.00 FL	*486.00 FL
19	1		*REAR UPPER TAIL LAMP RH	Serviceable	433.00 FL	*- FL
20	1		*REAR LOWER TAIL LAMP RH	Serviceable	486.00 FL	*- FL
21	1		*REAR END PANEL	Repair	629.00 FL	*- FL
22	1		*REAR END PANEL UPPER COVERING	Mtg Distorted	145.00 FL	*145.00 FL
23	1		*REAR FLOOR PANEL TOOLBOX TRAY	Serviceable	144.00 FL	*- FL
24	1		*REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	Serviceable	504.00 FL	*- FL
25	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
28	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
29	1		*REAR END PANEL JOINT SEALANT	Not Necessary	60.00 FS	*- FS
30	1		*REAR END PANEL UPPER COVERING CLIPS	Necessary	40.00 FS	*40.00 FS
					Sub Total (S\$)	8,618.00 3,350.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,007.00 762.53
					Total Parts (S\$)	6,611.00 2,587.57

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	1,000.00	450.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR TAILGATE OUTER GARNISH COVER ,REAR BUMPER ,REAR END PANEL & ETC	New	1,000.00	800.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	0.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	0.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS & ETC	New	150.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,600.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >