

ASS. REC. BY:

REF:

GRB/21012581/K

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 4177

Yr Regn:

10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1788

Colour

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

249878

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU103537280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / STD / RIM or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TOUR 900r

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/12/21

D.O.I.

14/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/12 21Rm \$3,100/- Ccdw

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Fees:

Others:

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Not Authorized
L1 Reg @ 3100/h
Running After Rain

4. days

Date: 13/12/2021
Vehicle No: SLH417Y
Model: TOYOTA PRIUS HYBRID 1.8CVT
Chassis: JTDKB3FU103537280-2016
Reg.Year: 2016

Third Party Insurer: INDIA
Third Party Veh No: SLS2512J
Date of Accident: 12/12/2021
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		R \$929.00
2	REAR TAILGATE OUTER GARNISH COVER	1		CM \$891.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		na \$75.00
4	REAR TAILGATE "PRIUS" EMBLEM	1		na \$75.00
5	REAR TAILGATE "TOYOTA" EMBLEM	1		na \$65.00
6	REAR TAILGATE INNER TRIM BOARD	1		su \$251.00
7	REAR TAILGATE INNER LOCK	1		R \$452.00
8	REAR TAILGATE WEATHERSTRIPE	1		su \$360.00
9	REAR WINDSCREEN MOULDING	1		na \$75.00
10	REAR BUMPER	1		bu \$448.00
11	REAR BUMPER SIDE BRACKET LH	1		su \$112.00
12	REAR BUMPER SIDE BRACKET RH	1		su \$112.00
13	REAR BUMPER LOWER GARNISH COVER	1		Red / na \$486.00
14	REAR BUMPER TOWING COVER	1		na \$25.00
15	REAR BUMPER ANTENNA SENSOR	1		CM \$75.00
16	REAR BUMPER REINFORCEMENT	1		na \$337.00
17	REAR UPPER TAIL LAMP LH	1		su \$433.00
18	REAR LOWER TAIL LAMP LH	1		amb / na \$486.00
19	REAR UPPER TAIL LAMP RH	1		su \$433.00
20	REAR LOWER TAIL LAMP RH	1		su \$486.00
23	REAR END PANEL	1		R \$629.00
24	REAR END PANEL UPPER COVERING	1		mb / DIT \$145.00
25	REAR FLOOR PANEL TOOLBOX TRAY	1		su \$144.00
26	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1		su \$504.00
SUB TOTAL				\$8,028.00
LESS 25%				-\$2,007.00
PARTS TOTAL				\$6,021.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1		na \$50.00
2	REAR WINDSCREEN SEALANT	1		na \$80.00
3	REAR BUMPER REVERSE SENSOR	1		Red \$300.00
4	REAR BUMPER CLIPS	1		na \$60.00
5	REAR END PANEL JOINT SEALANT	1		na \$60.00
6	REAR END PANEL UPPER COVERING CLIPS	1		na \$40.00
S/N TOTAL				\$590.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 13/12/2021
 Vehicle No: SLH417Y
 Model: TOYOTA PRIUS HYBRID 1.8CVT
 Chassis: JTDKB3FU103537280-2016
 Reg.Year: 2016

Third Party Insurer: INDIA
 Third Party Veh No: SLS2512J
 Date of Accident: 12/12/2021
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.	\$1,000.00	4501
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR TAILGATE OUTER GARNISH COVER, REAR BUMPER, REAR END PANEL & ETC.	\$1,000.00	8001
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.	nn \$150.00	X
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	nn \$120.00	X
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$100.00	501
TO TUFF KOTE & UNDERSEAL MATERIALS & ETC.	nn \$150.00	X
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	201
LABOUR TOTAL	\$2,600.00	

TING AN	TOTAL	\$9,211.00
---------	-------	------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

