

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21012582/KEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0000741\_02

**Claimant Vehicle No :** SLF8651U **Insured Vehicle No :** XE3898X

Date of Loss: 09/12/2021 Nature of Claim: TP Claim No: MFL2021D0005463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF8651U**

Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2ARU338938

Reg. Date: 14/09/2016 (Man. Year: 2016) Chassis No: MR053AK5004011473

Colour: Metallic Silver Odometer: 165096 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Maxxis 9 mm Rear Left Side: Maxxis 9 mm

Front Right Side: Maxxis 9 mm Rear Right Side: Maxxis 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,081.93	2,161.10	1,920.83	47.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,450.00	750.00	34.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,281.93</b>	<b>3,611.10</b>	<b>2,670.83</b>	<b>42.52</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,118.55</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,110.00</b>		

INSPECTION

Date of Assignment: 13/12/2021

Date Inspected: 14/12/2021 Inspected At: Ngs Automotive (HQ)

BLK 10 AMK IND PK 2A #02-01  
Singapore 568047

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2022)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8651U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	970.91 FL	*970.91 FL
2	8		*CLIPS ,FRT SUPPORT SEAL	Not Necessary	40.00 FL	*- FL
3	1		*SUPPORT PANEL (NPA)	Repair	0.00 FL	*- FL
4	1		*FENDER RH	Bent	394.35 FL	*394.35 FL
5	1		*BRACKET ,FRT SIDE RH	Distorted	58.11 FL	*58.11 FL
6	1		*FENDER LINING RH	Distorted	162.05 FL	*162.05 FL
7	12		*CLIPS ,FENDER LINING	Necessary	60.00 FL	*60.00 FL
8	1		*FRT BUMPER	Repair	596.48 FL	*- FL
9	1		*RETAINER ,FRT BUMPER RH	Distorted	109.50 FL	*109.50 FL
10	1		*FRT DOOR RH	Repair	1,584.46 FL	*- FL
11	1		*HEADLAMP RH	Cracked	987.01 FL	*987.01 FL
12	1		*MOULDING ,HEADLAMP RH	Scratched	86.39 FL	*86.39 FL
13	1		*EMBLEM VVTI FENDER RH	Necessary	53.15 FL	*53.15 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					5,102.41	2,881.47
- List Item Discount on L Items 20.00/25.00% (\$\$)					1,020.48	720.37
Total Parts (\$\$)					4,081.93	2,161.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT /ATTACHMENT STRAIGHT CHASSIS MEMBER REPAIR /RESHAPE DENTED BODY PANEL,REPLACE DAMAGED PART REFIT INTO POSITION	New	1,000.00	550.00
2	TO SPRAY PAINTING	New	1,000.00	880.00
3	TRANSFER FRT RH DOOR MECHANISM	New	150.00	0.00
4	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>2,200.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >