

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Autom	obile
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21012585/Utf3n2
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHC 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	14/01/2022
			Code:	AGI
1.		Policy Particulars	:- THIRD PARTY CLAI	М
	Insured Veh.	SMC 8641C	Veh. Inspected	SMC 5402X
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10012865/CD	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	13/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHD841CMJU717068	Colour	WHITE
	Odometer	58728 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 ZR17	ROADSTONE	6 mm
	L/H Front Tyre	215/45 ZR17	ROADSTONE	6 mm
	R/H Rear Tyre	215/45 ZR17	ROADSTONE	6 mm
	L/H Rear Tyre	215/45 ZR17	ROADSTONE	6 mm
4.	Description of Damages			
7.		Description	on of Damages	
7.	THE VEHICLE SU	STAINED DAMAGES AT THE RE		
7.	THE VEHICLE SU	STAINED DAMAGES AT THE RE		
5.		STAINED DAMAGES AT THE RE		
		STAINED DAMAGES AT THE RE	AR PORTION.	14/12/2021
	DAMAGES SEE D	STAINED DAMAGES AT THE RE ETAILS. Genera	I Information Inspection Date	14/12/2021
	DAMAGES SEE D	STAINED DAMAGES AT THE RE. ETAILS. General 12/12/2021	I Information Inspection Date	
	Accident Date Survey held at	STAINED DAMAGES AT THE RE. ETAILS. Genera 12/12/2021 XIN HUA WORKSHOP PTE LTE 23 KAKI BUKIT AVENUE 4 #04-	I Information Inspection Date Of (SOUTH WING) SING/	APORE 415933
5.	Accident Date Survey held at A)THE INSPECTION	STAINED DAMAGES AT THE RE. ETAILS. General 12/12/2021 XIN HUA WORKSHOP PTE LTE 23 KAKI BUKIT AVENUE 4 #04- RON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W	I Information Inspection Date Of (SOUTH WING) SING/	APORE 415933 IS.

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: