

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012588/TTY3N2**Date:** 14/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00119812100

**Claimant Vehicle  
No :** SKS4893H**Insured  
Vehicle No :** SLE2087T

Date of Loss: 10/12/2021

Nature of Claim: TP

Claim  
No: SNM21D207190/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKS4893H**

Make &amp; Model: MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)

Engine No: 4B12PL5271

Reg. Date: 20/04/2015 (Man. Year: 2015)

Chassis No: JMYXTGF3WZF001986

Colour: Maroon

Odometer: 125880 km

Engine Capacity: 2360 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,552.44	8,932.90	4,619.54	34.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	2,680.00	1,210.00	31.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,442.44</b>	<b>11,612.90</b>	<b>5,829.54</b>	<b>33.42</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,300.00</b>		
<b>(S\$)</b>	17,442.44	9,300.00	8,142.44	46.68
<b>+ GST 7.00/7.00% (S\$)</b>	1,220.97	651.00	569.97	46.68
<b>Nett Amount (S\$)</b>	<b>18,663.41</b>	<b>9,951.00</b>	<b>8,712.41</b>	<b>46.68</b>

**INSPECTION**

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021

Inspected At:

An-51 Automotive (HQ)  
2 KAKI BUKIT AVE 2 #01-18  
Singapore 417921

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 14 Apr 2022)

**Parts:** M1-SUV      MITSUBISHI OUTLANDER 2.4 CVT 4WD (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKS4893H)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	985.60 FL	*807.00 FL
2	2		*REAR BUMPER BRACKET L/R	Deformed	142.00 FL	*142.00 FL
3	1		*REAR BUMPER LOWER LID	Deformed	631.00 FL	*342.00 FL
4	12		*REAR BUMPER LOWER LID CLIPS	Necessary	36.00 FL	*36.00 FL
5	2		*REAR BUMPER REFLECTOR L/R	Cracked	180.00 FL	*180.00 FL
6	2		*REAR BUMPER SIDE GARNISH L/R	Deformed	256.00 FL	*256.00 FL
7	2		*REAR BUMPER SIDE RETAINER L/R	Deformed	50.00 FL	*50.00 FL
8	1		*REAR END PANEL	Bent	650.00 FL	*650.00 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Cracked	187.00 FL	*187.00 FL
10	1		*REAR END PANEL INNER TOP GARNISH	Deformed	158.00 FL	*158.00 FL
11	1		*REAR END PANEL KEYLESS SENSOR	Cracked	98.00 FL	*98.00 FL
12	1		*REAR FENDER INNER TRIM GARNISH L/R	O/s Deformed/N/s Not Necessary	1,854.00 FL	*796.00 FL
13	1		*REAR FLOOR PANEL	Repair	714.00 FL	*- FL
14	1		*REAR FLOOR PANEL CARGO TRAY BOX	Deformed	285.00 FL	*185.00 FL
15	1		*REAR FLOOR PANEL TOP BOARD COVER	Deformed	366.00 FL	*266.00 FL
16	1		*REAR SPARE TYRE CARRIAGE	Repair	425.00 FL	*- FL
17	1		*REAR SPARE TYRE CARRIAGE BRACKET	Repair	198.00 FL	*- FL
18	1		*REAR TAILGATE	Bent	1,154.00 FL	*989.00 FL
19	1		*REAR TAILGATE LOGO EMBLEM	Necessary	42.00 FL	*42.00 FL
20	1		*REAR TAILGATE MIVEC EMBLEM	Necessary	50.00 FL	*50.00 FL
21	1		*REAR TAILGATE OUTLANDER EMBLEM	Necessary	86.00 FL	*86.00 FL
22	1		*REAR TAILGATE BUTTON SENSOR SWITCH	Not Necessary	78.00 FL	*- FL
23	2		*REAR TAILGATE DAMPER L/R	Not Necessary	364.00 FL	*- FL
24	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	42.00 FL	*- FL
25	2		*REAR TAILGATE INNER RUBBER SIDE STOPPER L/R	Not Necessary	36.00 FL	*- FL
26	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	260.00 FL	*260.00 FL
27	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	28.00 FL	*- FL
28	1		*REAR TAILGATE MECHANISM LOCK	Bent	428.00 FL	*428.00 FL
29	1		*REAR TAILGATE OUTER GARNISH	Cracked	566.00 FL	*489.00 FL
30	2		*REAR TAILGATE SIDE SENSOR L/R	Distorted	968.00 FL	*770.00 FL
31	1		*REAR TAILGATE WEATHER STRIP	Cut	192.00 FL	*192.00 FL
32	1		*REAR TAILGATE WINDSCREEN LOWER MOULDING	Necessary	62.00 FL	*62.00 FL
33	2		*REAR TAILGATE WINDSCREEN MOULDING L/R	Necessary	110.00 FL	*110.00 FL
34	2		*REAR TAILLAMP L/R	Cracked	1,360.00 FL	*1,300.00 FL
35	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
36	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
37	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
38	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Necessary	100.00 FS	*20.00 FS
39	1		*REAR FLOOR PANEL INSULATOR MAT	Necessary	250.00 FS	*100.00 FS
40	1		*REAR TAILGATE C&C EMBLEM	Necessary	70.00 FS	*70.00 FS
41	1		*REAR TAILGATE CAMERA	Distorted	700.00 FS	*280.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
43	1		*REAR TAILGATE NUMBER PLATE HOLDER }	Bent	50.00 FS	*45.00 FS
44	1		*REAR TAILGATE NUMBER PLATE }	Bent	25.00 FS	*- FS
45	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
46	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
47	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,856.60	9,826.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,304.16	893.10
Total Parts (\$)	13,552.44	8,932.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	280.00	180.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR	New	60.00	30.00
3	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	140.00	60.00
5	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,500.00	1,200.00
6	TO REMOVE AND REINSTALL EXHAUST PIPE	New	100.00	0.00
7	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,500.00	1,000.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	30.00
9	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,890.00</b>	<b>2,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >