

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012589/KYA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJY6750D	Insured Vehicle No :	SLJ3400P
Date of Loss:	10/12/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005465

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6750D	Engine No:	1NZD464813
Make & Model:	TOYOTA AXIO, 1.5 X (A)	Chassis No:	NZE1416124196
Reg. Date:	23/09/2010 (Man. Year: 2009)	Odometer:	174409 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,261.50	8,795.77	10,465.73	54.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,940.00	2,210.00	42.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,411.50	11,735.77	12,675.73	51.93
Approved Total (Overridden) (S\$)		9,250.00		
Nett Amount (S\$)	24,411.50	9,250.00	15,161.50	62.11
+ Loss of Use (9.0 x S\$71.43/day) (S\$)		642.87		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,900.32		
Global Sum Settlement (S\$)		9,900.00		

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	14/12/2021	Inspected At: Autoworx House - Sin Ming (HQ) 176 SIN MING DRIVE #02-01 Singapore 575721
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2022)
Parts:	143	TOYOTA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY6750D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	846.40 FL	*846.40 FL
2	1		*REAR BOOT LID LOCK	Jammed	287.50 FL	*287.50 FL
3	1		*REAR BOOT LID LOCK CATCH	Repair	55.30 FL	*- FL
4	1		*REAR BOOT EMBLEM X	Necessary	54.40 FL	*54.40 FL
5	1		*REAR BOOT EMBLEM AXIO	Necessary	78.60 FL	*78.60 FL
6	1		*REAR BOOT EMBLEM COROLLA	Necessary	69.70 FL	*69.70 FL
7	1		*REAR BOOT EMBLEM LOGO	Necessary	68.10 FL	*68.10 FL
8	1		*REAR BOOT OUTER GARNISH	Warped	296.30 FL	*296.30 FL
9	1		*REAR BOOT WEATHERSTRIP (50%)	Dented / Distorted	293.03 FS	*195.35 FS
10	1		*REAR BOOT INNER TRIM	Serviceable	235.10 FL	*- FL
11	2		*REAR BOOT HINGE	Repair	391.00 FL	*- FL
12	1		*REAR END PANEL	Bent	574.40 FL	*574.40 FL
13	1		*REAR END PANEL GARNISH	Mtg Distorted	325.00 FL	*325.00 FL
14	2		*REAR TAIL LAMP ASSY	Mtg Cracked	1,127.20 FL	*735.00 FL
15	2		*REAR TAIL LAMP HOUSING PANEL	Repair	749.00 FL	*- FL
16	1		*REAR BUMPER	Bent	1,052.90 FL	*565.20 FL
17	2		*REAR BUMPER SIDE RETAINER	Distorted	112.00 FL	*112.00 FL
18	1		*REAR BUMPER IMPACT BRACKET	N/S Bent	358.00 FL	*179.00 FL
19	2		*REAR BUMPER CORNER RETAINER	Distorted	175.20 FL	*175.20 FL
20	1		*REAR SPARE TYRE PANEL	Repair	687.60 FL	*- FL
21	1		*REAR SPARE TYRE TOP BOARD	Cracked	367.40 FL	*367.40 FL
22	1		*REAR EXHAUST SILENCER	Repair	1,421.10 FL	*- FL
23	1		*REAR EXHAUST SILENCER HEAT SHIELD	Serviceable	345.40 FL	*- FL
24	1		*FRONT BONNET	Bent	675.90 FL	*675.90 FL
25	1		*FRONT BONNETSTAY ROD	Serviceable	87.10 FL	*- FL
26	1		*FRONT BONNETSTAY ROD GOMMET	Serviceable	7.60 FL	*- FL
27	1		*FRONT BONNET LOCK	Repair	176.40 FL	*- FL
28	1		*FRONT BONNET LOCK CABLE	Serviceable	156.70 FL	*- FL
29	1		*FRONT BONNET RUBBER SEAL	Serviceable	95.30 FL	*- FL
30	2		*FRONT HEAD LAMP ASSY	Mtg Cracked	1,514.60 FL	*1,514.60 FL
31	2		*FRONT HEAD LAMP PANEL	Repair	632.60 FL	*- FL
32	1		*RADIATOR	Bent	1,079.50 FL	*1,079.50 FL
33	1		*RADIATOR TOP BRACKET	Serviceable	97.40 FL	*- FL
34	1		*RADIATOR FAN COWLING	Serviceable	216.40 FL	*- FL
35	1		*RADIATOR FAN MOTOR	Serviceable	364.50 FL	*- FL
36	1		*RADIATOR FAN BLADE	Serviceable	195.40 FL	*- FL
37	1		*FRONT RADIATOR TOP PANEL	Repair	265.70 FL	*- FL
38	1		*FRONT RADIATOR CENTRE BRACE PANEL	Repair	196.70 FL	*- FL
39	1		*FRONT RADIATOR LOWER PANEL	Repair	233.40 FL	*- FL
40	2		*FRONT RADIATOR SIDE PANEL	Repair	535.60 FL	*- FL
41	2		*HORN	Serviceable	352.80 FL	*- FL
42	1		*FRONT BUMPER	Buckled	678.10 FL	*645.10 FL
43	2		*FRONT BUMPER FOG LAMP GARNISH	Serviceable	268.60 FL	*- FL
44	1		*FRONT BUMPER TOP GRILLE	Serviceable	386.50 FL	*- FL
45	2		*FRONT BUMPER FOG LAMP	Serviceable	878.20 FL	*- FL
46	1		*FRONT BUMPER REINFORCEMENT	Bent	331.40 FL	*331.40 FL

Report was unsubmitted during this print-out.

5/18/23, 10:23 PMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER IMPACT SPONGE	Cracked	198.90 FL	*138.00 FL
48	2		*FRONT BUMPER SIDE RETAINER	Distorted	149.00 FL	*149.00 FL
49	10		*FRONT BUMPER CLIP	Necessary	31.00 FL	*31.00 FL
50	1		*AIR CON CONDENSER	Bent	1,465.20 FL	*1,288.00 FL
51	1		*AIR CON LIQUID PIPE	Serviceable	278.70 FL	*- FL
52	1		*AIR CON HIGH PRESSURE HOSE	Serviceable	325.30 FL	*- FL
53	2		*FRONT FENDER	Repair	1,156.40 FL	*- FL
54	2		*FRONT FENDER DUST COVER	Serviceable	395.20 FL	*- FL
55	1		*FRONT FENDER DUST COVER CLIP (24 PCS)	Not Necessary	74.40 FL	*- FL
56	1		*FRONT GRILLE	Cracked	577.40 FL	*381.40 FL
57	1		*FRONT GRILLE EMBLEM	Necessary	94.30 FL	*61.00 FL
58	8		*FRONT GRILLE CLIP	Necessary	24.80 FL	*24.80 FL
59	1		*AIR TEMPERATURE SENSOR	Serviceable	215.90 FL	*- FL
60	1		*SET REVERSE SENSOR	Dented	220.00 FS	*220.00 FS
61	1		*SET REVERSE CAMERA	Serviceable	460.00 FS	*- FS
62	2		*NUMBER PLATE }	Dented	70.00 FS	*90.00 FS
63	2		*NUMBER PLATE CASING }	Dented	70.00 FS	*- FS
64	1		*BOT RADIATOR COOLANT	Not Necessary	80.60 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	25,284.13	11,559.25
- List Item Discount on L Items 25.00/25.00% (S\$)	6,022.63	2,763.48
Total Parts (S\$)	19,261.50	8,795.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECED AREAS	New	1,600.00	1,000.00
2	TO INSTALL REVERSE SENSOR AND CAMERA	New	120.00	60.00
3	TO CHECK WIRING SYSTEM	New	60.00	40.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	90.00
5	TO APPLY WATERPROOF SEALANT ON WEILDED PANELS	New	150.00	30.00
6	TO SPRAY PAINTING ON AFFECTED AREAS	New	2,100.00	1,400.00
7	TO REPLACE AIR CON COMPONENTS AND TOP UP GAS	New	140.00	100.00
8	TO BENCH MOUNT & ALIGN CHASSIS FRAME	New	480.00	0.00
9	TO CARRY OUT EXHAUST WORK	New	140.00	60.00
10	TO INSTALL REVERSE SENSOR & CAMERA	New	80.00	50.00
11	TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR	New	80.00	60.00
12	TOWING CHARGES	New	50.00	50.00
Gross Labour Cost (S\$)			5,150.00	2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >