

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21012592/Bvy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	07/01/2022	
	ATTN: KOH JANIC	E		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	FBL 7654E	Veh. Inspected		FBQ 8308Y	
	Policy No.	P2408328	Coverage (\$)		0.00	
	Claim No.	S1M03O5D	Excess (\$)		0.00	
	Assign From	KOH JANICE	Assign Date		13/12/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA FS150F	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	PMKKC2760KB221451	Colour		BLUE	
	Odometer	12375 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90/17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	110/70/17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5.	General Information					
	Accident Date	06/09/2021	Inspect Date /	Time	14/12/2021 ( 03:47 PM )	
	Survey held at	160 Sin Ming Drive #05-17, Sin N	Ming Autocity			
	Repairer HIAP LEK AUTOMOBILE TRADING					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
5b.	bb. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21012592/Bvy3e2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

**Automotive Assessor** 

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$ 

REGD Auto Consultant-SAE, Licensed Appraiser