

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012593/GEA3Q2**Date:** 30/05/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100423698
Claimant Vehicle No :	SHB1881L	Insured Vehicle No :	SCR5502E
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	9970738380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1881L	Engine No:	2ZR1443855
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U405752079
Reg. Date:	03/10/2014 (Man. Year: 2013)	Odometer:	0 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	ATREZZO 6 mm	Rear Left Side:	ATREZZO 6 mm
Front Right Side:	ATREZZO 6 mm	Rear Right Side:	ATREZZO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,632.68	1,688.58	9,944.10	85.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,239.00	750.00	2,489.00	76.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,871.68	2,438.58	12,433.10	83.60
Approved Total (Overridden) (S\$)		2,150.00		
Nett Amount (S\$)	14,871.68	2,150.00	12,721.68	85.54
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
+ Car Rental (8.0 x S\$100.58/day) (S\$)		804.64		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,361.64		
Global Sum Settlement (S\$)		3,360.00		

INSPECTION

Date of Assignment:	10/12/2021	
Date Inspected:	10/12/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER LIP REAR (DISC 25%)	Deformed	228.90 F	*171.68 F
2	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Deformed	118.10 F	*88.58 F
3	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
4	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
5	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
6	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Cracked	139.60 F	*104.70 F
7	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Cracked	94.80 F	*71.10 F
8	1		*ANTENNA ELECTRICAL LOWER REAR (DISC 10%)	Necessary	157.40 F	*141.66 F
9	1		*SENSOR REVERSE (SN)	Damaged	180.00 F	*180.00 F
10	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
11	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
12	1		*TAIL LAMP BRACKET RH	Not Necessary	30.70 F	*- F
13	1		*TAIL LAMP RH	Not Necessary	557.80 F	*- F
14	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
15	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
16	1		*FENDER RR/RH	Not Necessary	766.80 F	*- F
17	1		*SPOILER REAR	Not Necessary	953.70 F	*- F
18	1		*NAME PLATE (TOYOTA)	Not Necessary	51.90 F	*- F
19	1		*NAME PLATE (PRIUS)	Not Necessary	60.80 F	*- F
20	1		*NAME PLATE (HYBRID)	Not Necessary	51.90 F	*- F
21	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
22	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
23	1		*EMBLEM REAR	Not Necessary	60.30 F	*- F
24	1		*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*- F
25	1		*TAILGATE DOOR WEATHERSTRIP	Not Necessary	353.40 F	*- F
26	1		*TAILGATE ASY	Not Necessary	1,007.90 F	*- F
27	1		*SUPPORT EXHAUST REAR	Not Necessary	33.60 F	*- F
28	1		*EXHAUST TAIL PIPE	Not Necessary	656.20 F	*- F
29	1		*SPARE TYRE PANEL	Not Necessary	667.70 F	*- F
30	1		*BOX ,DECK FLOOR RR	Not Necessary	649.70 F	*- F
31	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
32	1		*END PANEL COVER DECK TRIM RR	Not Necessary	121.10 F	*- F
33	1		*END PANEL COVER DECK TRIM HOLE	Not Necessary	46.10 F	*- F
34	1		*UNDER COVER RR SHIELD	Not Necessary	63.90 F	*- F
35	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Not Necessary	514.50 F	*- F
36	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
37	1		*BUMPER SEAL ,RR RH	Not Necessary	65.70 F	*- F
38	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
39	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
40	1		*ANTENNA ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
41	1		*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
42	1		*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
43	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
44	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
45	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
46	1		*END PANEL	Repair	602.10 F	*- F
47	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F

F=Franchise part.

Total Parts (\$\$) 11,632.68 1,688.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	2,034.00	300.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$)			3,239.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >