

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012595/GPA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SHC4745Y **Insured Vehicle No :** GBH4865D
 Date of Loss: 06/12/2021 Nature of Claim: TP Claim No: 4487676063SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC4745Y**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR1651940
 Reg. Date: 08/01/2016 (Man. Year: 2015) Chassis No: JTDKN36U205766756
 Colour: Maroon Odometer: 0 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: ATREZZO 6 mm Rear Left Side: ATREZZO 6 mm
 Front Right Side: ATREZZO 6 mm Rear Right Side: ATREZZO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,905.98	776.58	2,129.40	73.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,256.00	430.00	826.00	65.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,161.98	1,206.58	2,955.40	71.01
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	4,161.98	1,100.00	3,061.98	73.57
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (5.0 x S\$103.26/day) (S\$)		516.30		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,773.30		

INSPECTION

Date of Assignment: 10/12/2021
 Date Inspected: 10/12/2021 Inspected At: Strides Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Cut	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
3	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
4	1		*ADVERTISEMENT STICKER (SN)	No	296.88 F	*296.88 F
5	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
6	1		*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
7	1		*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
8	1		*ANTENNA ,ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
9	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
10	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
11	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
12	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
13	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
14	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
15	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Not Necessary	514.50 F	*- F
16	1		*UNDER COVER RR SHIELD	Not Necessary	63.90 F	*- F

F=Franchise part.

Total Parts (S\$) 2,905.98 776.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
			Gross Labour Cost (\$)	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >