

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012598/AYA3Q2**Date:** 01/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SKD699H **Insured Vehicle No :** SLH8700B
 Date of Loss: 09/12/2021 Nature of Claim: TP Claim No: MFL2021D0005464

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD699H**
 Make & Model: MERCEDES-BENZ GLS400, 3.0 4MATIC AUTO (A) Engine No: 65692980083301
 Reg. Date: 16/10/2020 (Man. Year: 2019) Chassis No: W1N1679232A149581
 Colour: Black Odometer: 30084 km
 Engine Capacity: 2925 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 325/40 R22 Rear Tyre Size: 325/40 R22
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,082.00	3,222.00	8,860.00	73.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	660.00	2,390.00	78.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,132.00	3,882.00	11,250.00	74.35
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	15,132.00	3,100.00	12,032.00	79.51
+ GST 7.00/7.00% (\$\$)	1,059.24	217.00	842.24	79.51
Nett Amount (\$\$)	16,191.24	3,317.00	12,874.24	79.51
+ Car Rental (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,124.45		

INSPECTION

Date of Assignment: 13/12/2021
 Date Inspected: 06/01/2022 Inspected At: Jack Cars Enterprise Pte Ltd - Ubi (HQ)
 BLK 3007 UBI ROAD 1 #01-450
 Singapore 408701
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2022)
Parts:	143	MERCEDES-BENZ GLS400 3.0 4MATIC AUTO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD699H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,200.00 FL	*2,350.00 FL
2	1		*REAR BUMPER DIFFUSER (CENTRE LEFT & RIGHT)	Deformed	900.00 FL	*550.00 FL
3	1		*REAR BUMPER INNER BRACKET	Not Necessary	90.00 FL	*- FL
4	1		*REAR BUMPER CHROME GARNISH	Cracked	380.00 FL	*380.00 FL
5	1		*REAR END PANEL	Repair	980.00 FL	*- FL
6	1		*LEFT TAILLAMP -OUTER	Not Necessary	2,200.00 FL	*- FL
7	1		*EXHAUST PIPE	Not Necessary	4,500.00 FL	*- FL
8	1		*EXHAUST TIP	Not Necessary	270.00 FL	*- FL
9	1		*EXHAUST HEAT SEAL	Not Necessary	310.00 FL	*- FL
10	1		*CLIPS ,SCREWS & RIVETS	Necessary	100.00 FS	*50.00 FS
11	1		*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS
12	1		*TOW HOOK COVER -REAR	Not Necessary	95.00 FS	*- FS
13	1		*REFLECTOR -REAR LEFT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,365.00	3,550.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,283.00	328.00
Total Parts (\$\$)	12,082.00	3,222.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,000.00	250.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS KNOCK JACK WELD ,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	800.00	300.00
3	TO CHECK LIGHTING SYSTEM WIRING & REWIRE	New	350.00	50.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	220.00	0.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	280.00	0.00
6	TO REMOVE & REINSTALL SENSORS	New	200.00	60.00
7	ANTI RUST TREATMENT	New	200.00	0.00
Gross Labour Cost (S\$)			3,050.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >