

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21012609/ETF3E2

**Date:** 05/01/2022

### REFERENCE

Insured/Claimant: TEO PENG CHONG (ZHANG BINCONG)  
Date of Loss: 12/12/2021

Policy No:  
Nature of Claim: OD Claim No: 9009443567SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW3232J	Engine No:	G4FGJH709506
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5020200
Reg. Date:	26/11/2018 (Man. Year: 2018)	Odometer:	49488 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$71,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,915.00	4,436.00	2,479.00	35.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	3,200.00	1,270.00	28.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,385.00</b>	<b>7,636.00</b>	<b>3,749.00</b>	<b>32.93</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>10,785.00</b>	<b>7,036.00</b>	<b>3,749.00</b>	<b>34.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>754.95</b>	<b>492.52</b>	<b>262.43</b>	<b>34.76</b>
<b>Nett Amount (S\$)</b>	<b>11,539.95</b>	<b>7,528.52</b>	<b>4,011.43</b>	<b>34.76</b>

### INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 9.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, RH	Broken	1,219.00 F	*1,219.00 FL
3	1		*COVER-FR BUMPER	Broken	633.00 F	*633.00 FL
4	1		*GRILLE-FRONT FENDER	Broken	262.00 F	*262.00 FL
5	1		*GRILLE-ASSY RADIATOR	Not Necessary	328.00 F	*- FL
6	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
7	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 F	*- FL
8	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 F	*143.00 FL
9	1		*MOULDING-FRONT BUMPER, RH	Broken	36.00 F	*36.00 FL
10	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	303.00 F	*- FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 F	*22.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 F	*- FL
13	1		*PANEL ASSY-HOOD	Dented	1,502.00 F	*1,502.00 FL
14	1		*PANEL-FENDER, RH	Dented	430.00 F	*430.00 FL
15	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 F	*- FL
16	1		*ORNAMENT-KIA NO.115	Necessary	32.00 F	*32.00 FL
17	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 F	*- FL
18	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 F	*675.00 FL
19	1		*AIR DUCT - FRONT BUMPER RH	Broken	14.00 F	*14.00 FL
20	1		(Supplementary) *CLIP (10PCS)	Necessary	10.00 F	*10.00 FL
21	1		(Supplementary) *RESERVOIR & PUMP ASSY - WASHER	Crushed	146.00 F	*146.00 FL
22	1		(Supplementary) *COLLANT (4L)	Necessary	26.00 F	*26.00 FL
23	1		(Supplementary) *ARM COMPLETE - FR LWR, RH	Bent	286.00 F	*286.00 FL
					<b>Sub Total (S\$)</b>	<b>6,915.00      5,540.00</b>
					<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	<b>0.00      1,104.00</b>
					<b>Total Parts (S\$)</b>	<b>6,915.00      4,436.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER RH. REPAIR FRT DOOR RH	New	1,920.00	1,000.00
2	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT DOOR RH	New	1,400.00	1,050.00
3	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
8	STRAIGHTEN FRONT CHASSIS (Supplementary)	New	500.00	500.00
9	VACUUM & TOP UP AIRCON GAS (Supplementary)	New	80.00	80.00
10	RENWQ FRONT UNDER CARRIAGE (Supplementary)	New	160.00	160.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,470.00</b>	<b>3,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >