



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
TEO PENG CHONG (ZHANG BINGCONG)	Cust No/Name	/TEO PENG CHONG (ZHANG BINGCONG)
65 SARACA TERRACE	Reg No/Reg Date	SDW3232J / 26/11/201
SINGAPORE 805501	Date In/Mileage	/ 0
Contact No Mobile: 97673132	Chassis No	KNAF3416MK5020200
	Engine No	G4FGJH709506
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	13/12/2021/ 16:37	BLC	442 / CocoLu	43941			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200 1920.00
RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER RH					2.5			
REPAIR FRT DOOR RH,								1050 1400.00
E PNT98000								
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT DOOR RH					4			100.00
E PNT88000								
REMOVE & INSTALL AIRCON CONDENSOR & RAIDIATOR								30.00
A 90000001								120.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								40.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								20.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								120.00
M SUNDRY								
Sundry								
B WHEEL ALIGNMENT								
To Conduct Computerize Full Wheel Alignment								
M LAMP ASSY-HEAD, RH					1.00	1219.00	00.00	1219.00
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER					1.00	262.00	00.00	262.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	328.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
M GARNISH-RADIATOR GRILLE					1.00	38.00	00.00	38.00
M LAMP ASSY-SIDE REPEATER, RH					1.00	143.00	00.00	143.00
M MOULDING-FRONT BUMPER, RH					1.00	36.00	00.00	36.00
M LAMP ASSY-FRONT FOG, RH					1.00	303.00	00.00	303.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	00.00	22.00
M STIFFNER-FR BPR LWR					1.00	114.00	00.00	114.00
M PANEL ASSY-HOOD					1.00	1502.00	00.00	1502.00
M PANEL-FENDER, RH					1.00	430.00	00.00	430.00
M GUARD ASSY-FRONT WHEEL, RH					1.00	95.00	00.00	95.00
M ORNAMENT-KIA NO.115					1.00	32.00	00.00	32.00
M BEAM COMPLETE-FR BUMPER					1.00	497.00	00.00	497.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
TEO PENG CHONG (ZHANG BINGCONG)	Cust No/Name	/TEO PENG CHONG (ZHANG BINGCONG)
65 SARACA TERRACE	Reg No/Reg Date	SDW3232J / 26/11/201
SINGAPORE 805501	Date In/Mileage	/ 0
Contact No Mobile: 97673132	Chassis No	KNAF3416MK5020200
	Engine No	G4FGJH709506
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	13/12/2021/ 16:37	BLC	442 / CocoLu	43941			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M CARRIER ASSY-FRONT END MODULE 1 br					1.00	675.00	00.00	675.00

Estimate

Steve (LKK)
 14/12/21, 11.00am

PD - AL AL
 Excess - ?
 P/P
 M P/L
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer
 Signature:
 Date:

7% GST on	10163.00	10,163.00
		711.41
Total Payable		10,874.41

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.