

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012610/EQF3N2**Date:** 28/01/2022**REFERENCE**

Insured/Claimant: PANG KOK WEE, DAVID (PAN GUOWEI, DAVID)
Date of Loss: 13/12/2021

Policy No: 1900001478

Nature of Claim: OD Claim No: 6785404327SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH357A**
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 (A) Engine No: 4B40GB9312
Reg. Date: 09/01/2019 (Man. Year: 2018) Chassis No: JMAXTGK1WJZ004786
Colour: White Odometer: 37668 km
Engine Capacity: 1499 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,914.88	3,324.84	1,590.04	32.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	2,270.00	490.00	17.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,674.88	5,594.84	2,080.04	27.10
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	7,274.88	5,194.84	2,080.04	28.59
+ GST 7.00/7.00% (S\$)	509.24	363.64	145.60	28.59
Nett Amount (S\$)	7,784.12	5,558.48	2,225.64	28.59

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,LH	Broken	1,986.00 FL	*1,986.00 FL
2	1		*COVER,FR BUMPER	Cut	382.00 FL	*382.00 FL
3	1		*FACE,FR BUMPER	Broken	664.00 FL	*664.00 FL
4	1		*GARNISH,FR BUMPER SIDE	Broken	73.00 FL	*73.00 FL
5	1		*GARNISH,FR BUMPER SIDE	Broken	214.00 FL	*214.00 FL
6	1		*BRKT,F/BMPR T/SIG LAMP LH	Not Necessary	17.00 FL	*- FL
7	1		*BAR,FR BUMPER GUARD	Not Necessary	100.00 FL	*- FL
8	1		*REINFORCEMENT,FR BUMPER	Not Necessary	555.00 FL	*- FL
9	1		*REINFORCEMENT,FR BUMPER	Dented	236.00 FL	*236.00 FL
10	1		*STAY,FR BUMPER	Not Necessary	9.00 FL	*- FL
11	1		*REINF,FR BUMPER SIDE,LH	Bent	35.00 FL	*35.00 FL
12	1		*BRACKET,FR BUMPER SIDE,LH	Not Necessary	18.00 FL	*- FL
13	1		*EXTENSION,FR BUMPER	Cut	318.00 FL	*318.00 FL
14	1		*GRILLE ASSY,RADIATOR	Not Necessary	486.00 FL	*- FL
15	1		*COVER,FR BUMPER GRILLE	Not Necessary	302.00 FL	*- FL
16	1		*PNL,HEADLAMP SUPT,UPR LH	Not Necessary	59.00 FL	*- FL
17	1		*LAMP A,T/SIG & FOG,FR LH	Not Necessary	506.00 FL	*- FL
18	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
19	1		*FRONT BUMPER GARNISH (Supplementary)	Cut	384.00 FL	*384.00 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					6,374.00	4,312.00
- List Item Discount on L Items 23.00/23.00% (S\$)					1,459.12	987.16
Total Parts (S\$)					4,914.88	3,324.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER PANEL,FRT LH HEADLAMP PANEL & AFFECTED AREA	New	900.00	450.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	80.00
4	PERFORM RUST PREVENTION	New	40.00	40.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	TO SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	SPRAY PAINT ON FRONT LH FENDER (Supplementary)	New	350.00	350.00
9	REPAIR FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
10	SPRAY PAINT FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			2,760.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >