

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21012616/UQF3N2**Date:** 28/12/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJC6485K**Insured Vehicle No :** SMK4406A

Date of Loss: 09/12/2021

Nature of Claim: TP

Claim No: 2571556025SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJC6485K**

Make & Model: HONDA CIVIC, 1.3 EC8 (M)

Engine No: R16A13002557

Reg. Date: 26/02/2008 (Man. Year: 2008)

Chassis No: JHMFD46208S200905

Colour: Black

Odometer: 247006 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size: 225/45R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,696.88	1,456.16	2,240.72	60.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	570.00	1,330.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,596.88	2,026.16	3,570.72	63.80
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	5,596.88	1,600.00	3,996.88	71.41

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At:

Unimotor Company - Kaki Bukit (HQ)
1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Not Necessary	214.60 FL	*- FL
2	1		*L/H FRONT HEADLAMP ASSY (HID) UNIT	Cracked	1,876.40 FL	*903.20 FL
3	1		*L/H FRONT HEADLAMP LOWER BRACKET	Repair	89.60 FL	*- FL
4	1		*FRONT BUMPER FACE	Deformed/Torn	883.60 FL	*692.40 FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	435.50 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	117.60 FL	*- FL
7	1		*FRONT RADIATOR GRILLE ASSY	Cracked	378.80 FL	*224.60 FL
8	1		*FRONT NUMBER PLATE ASSY	Not Necessary	50.00 FS	*- FS
9	1		*FRONT BUMPER LOWER SPOILER	Repair	450.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,496.10	1,820.20
- List Item Discount on L Items 20.00/20.00% (\$\$)					799.22	364.04
Total Parts (\$\$)					3,696.88	1,456.16

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/REWIRE DAMAGED PORTION	New	100.00	20.00
2	TO DISM/RENEW FRONT LOWER SPOILER	New	100.00	0.00
3	TO PANEL BEAT DAMAGED PORTION	New	800.00	250.00
4	TO PUTTY AND RESPRAY DAMAGED PORTION	New	800.00	300.00
5	TO SPRAY UNDERCOATING IN REPAIR	New	100.00	0.00
Gross Labour Cost (\$)			1,900.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >