

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21012620/T1VF3E2

**Date:** 27/01/2022

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070116205  
Claimant Vehicle No : SG5318P Insured Vehicle No : SMV968M  
Date of Loss: 10/12/2021 Nature of Claim: TP Claim No: 0176011626SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5318P**  
Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9194961  
Reg. Date: 07/03/2016 (Man. Year: 2015) Chassis No: YV3S4P921GA176443  
Colour: Multi-colour Odometer: 477718 km  
Engine Capacity: 9364 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,726.00	1,726.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,384.00	2,200.00	184.00	7.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,110.00</b>	<b>3,926.00</b>	<b>184.00</b>	<b>4.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>287.70</b>	<b>274.82</b>	<b>12.88</b>	<b>4.48</b>
<b>Nett Amount (S\$)</b>	<b>4,397.70</b>	<b>4,200.82</b>	<b>196.88</b>	<b>4.48</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 14/12/2021  
Date Inspected: 15/12/2021 Inspected At: Sbs Transit Ltd ( Bedok) (HQ)  
1470 BEDOK NORTH AVE 4  
Singapore 489946  
Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT MID BUMPER COMP MOULD-CL 2;FRT	Cracked	260.00 F	*260.00 F
2	1		*FRONT WINDSCREEN.LOW/S	Cracked	950.00 F	*950.00 F
3	1		*MAIN BEAM HEADLAMP	Cut	58.00 F	*58.00 F
4	1		*DIPPED BEAM HEADLAMP	Cut	68.00 F	*68.00 F
5	1		*O/S CORNER BUMPER COMP MOULD-CL 2;FRT	Cracked	230.00 F	*230.00 F
6	1		*FRT OS CORNER DEFLECTOR COMP MOULD CL2	Cracked	65.00 F	*65.00 F
7	1		*FRT O/S LIGHT BEZEL COMP MOULD-CL 2;FRT	Cracked	95.00 F	*95.00 F
Total Parts (S\$)					1,726.00	1,726.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTOR LABOUR COST	New	2,200.00	2,200.00
2	WORKSHOP LABOUR COST	New	184.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,384.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >