

ASS. REC. BY:

Tanjun

REF:

CS/A162122620/TIVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SMV 968M

Policy No.

2070116205

Claims No.

0176011626SG

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Simon

Veh No:

SG5318P

Yr Regn:

2016, Mach

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo B9TL

c.c

9364

Colour

Multi

A/C:

Insured / Std / NI / NA

Sp. Reading

477718

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YV354P921G M76443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NIP / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

22 (D)

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A. 10/12/21

D.O.I.

15/12/21 11/24

Survey held at

Bedok Bus Depot

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt, Frt/Ls

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MS will give estimate

19/1/22

Submit \$3926 (un-confirmed) (Red 184, 4%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 19/1/22-typist

Rep. Format:

Lump Sum / L.B.A. ()

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

