



Accident Reference & Bus No: E/5346/2021 - SG5318P with SMV968M

Activated date: Mon 13/12/2021 20:08

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Name of Surveyor: Mr. Taufikh

Company Name: LKK Auto

Date Surveyed: 15/12/2021, 10:00am

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30112004	FRT MID BUMPER COMP MOULD-CL 2;FRT	1	\$260.00
30750015	FRONT WINDSCREEN.LOW/S	1	\$950.00
30541665	MAIN BEAM HEADLAMP	1	\$58.00
30541666	DIPPED BEAM HEADLAMP	1	\$68.00
30112003	O/S CORNER BUMPER COMP MOULD-CL 2;FRT	1	\$230.00
30750000	FRT OS CORNER DEFLECTOR COMP MOULD CL2	1	\$65.00
30112002	FRT O/S LIGHT BEZEL COMP MOULD-CL 2;FRT	1	\$95.00

- ☐ Parts cost: \$ 1726.00
☐ Contractor Labour cost: \$ 2200.00 + GST ✓
☐ Workshop Labour cost: \$ 184.00 Xnn.
☐ Advertisement Cost: \$ 0 4110
☐ Repair period: 3 days

- ☐ Tow Cost: \$ 0
☐ Loss of use: Not required by surveyor Xnn
☐ Overheads: Not required by surveyor Xnn

Taufikh 97495749
 15/12/21 @ 1115
 Resurvey new parts
 taufikh@lkkauto.com
 03 days
 CRK not finished with w/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: