

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21012628/ETF3N2**Date:** 12/01/2022REFERENCE

Insured/Claimant: TING MIN WEE, BERNARD (CHEN MINGWEI, BERNARD) Policy No: 1900104004

Date of Loss: 11/12/2021

Nature of Claim: OD

Claim No: 3868242188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM6952R</b>	Engine No:	3A92UHM3658
Make & Model:	mitsubishi attrage, 1.2 (A)	Chassis No:	MMBSTA13AKH000729
Reg. Date:	10/07/2019 (Man. Year: 2018)	Odometer:	22307 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,331.00	5,965.42	3,365.58	36.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,935.00	8,360.00	2,575.00	23.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,266.00</b>	<b>14,325.42</b>	<b>5,940.58</b>	<b>29.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,418.62</b>	<b>1,002.78</b>	<b>415.84</b>	<b>29.31</b>
<b>Nett Amount (S\$)</b>	<b>21,684.62</b>	<b>15,328.20</b>	<b>6,356.42</b>	<b>29.31</b>

INSPECTION

Date of Assignment: 14/12/2021

Date Inspected: 14/12/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 16.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
2	1		*FACE,RR BUMPER	Dented	751.00 F	*751.00 FL
3	1		*BRACKET,RR BUMPER,LH	Broken	28.00 F	*28.00 FL
4	1		*BRACKET,RR BUMPER,RH	Broken	28.00 F	*28.00 FL
5	1		*WEATHERSTRIP,TRUNK LID	Crushed	157.00 F	*157.00 FL
6	1		*PANEL,TRUNK LID	Dented	795.00 F	*795.00 FL
7	1		*HINGE TRUNK LID,RH	Bent	203.00 F	*203.00 FL
8	1		*HINGE TRUNK LID,LH	Bent	203.00 F	*203.00 FL
9	1		*LATCH,TRUNK LID	Bent	218.00 F	*218.00 FL
10	1		*PANEL,RR END	Dented	427.00 F	*427.00 FL
11	1		*PANEL,RR COMB LAMP HSG,RH	repair	60.00 F	-
12	1		*PANEL,RR COMB LAMP HSG,LH	Dented	60.00 F	*60.00 FL
13	1		*GARNISH,RR END PANEL	Not Necessary	336.00 F	*- FL
14	1		*MARK,THREE-DIA	Necessary	70.00 F	*70.00 FL
15	1		*MARK,ATTRAGE	Necessary	21.00 F	*21.00 FL
16	1		*BOARD LUGGAGE RIIM PARTN	Not Necessary	172.00 F	*- FL
17	1		*BOARD,TRUNK ROOM FLOOR	Broken	195.00 F	*195.00 FL
18	1		*TRIM,RR END	Crushed	66.00 F	*66.00 FL
19	1		*TRIM,TRUNK ROOM SIDE,RH	Crushed	160.00 F	*160.00 FL
20	1		*TRIM,TRUNK ROOM SIDE,LH	Crushed	160.00 F	*160.00 FL
21	1		*REFLECTOR	Not Necessary	23.00 F	*- FL
22	1		*REFLECTOR	Not Necessary	23.00 F	*- FL
23	1		*LAMP ASSY,COMB,RR LH	Broken	337.00 F	*337.00 FL
24	1		*LAMP ASSY,COMB,RR RH	Broken	337.00 F	*337.00 FL
25	1		*LAMP ASSY,LICENSE PLATE	Not Necessary	51.00 F	*- FL
26	1		*BUZZER,KEYLESS OPERATIO,RR	Broken	91.00 F	*91.00 FL
27	1		*ANT,KEYLESS OPERATION RR	Not Necessary	96.00 F	*- FL
28	1		*DUCT,RR VENTILATOR	Not Necessary	30.00 F	*- FL
29	1		*COVER,RR VENTILATOR	Crushed	40.00 F	*40.00 FL
30	1		*PIPE,EXHAUST TAIL	Not Necessary	603.00 F	*- FL
31	1		*MUFFLER,EXHAUST MAIN	Not Necessary	788.00 F	*- FL
32	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
33	1		*PARKING SENSOR	Shorted	220.00 FS	*220.00 FS
34	1		*REAR NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
35	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
36	1		*CLIP, FR BUMPER (10PCS) Supplementary	Necessary	40.00 F	*40.00 FL
37	1		*PANEL, QTR, OTR LH Supplementary	Dented	759.00 F	*759.00 FL
38	1		*EMBLEM MIVEC TECHNOLOGY Supplementary	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,331.00</b>	<b>7,149.00</b>
<b>- List Item Discount on L Items 0.00/23.00% (\$)</b>	0.00	1,183.58
<b>Total Parts (\$)</b>	<b>9,331.00</b>	<b>5,965.42</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW REAR AIRDAM,REAR BUMPER,BOOTLID,REAR END PANEL,REAR LAMP HOUSING RH & LH,REPAIR REAR FENDER RH & LH	New	4,050.00	2,925.00
2	REMOVE & INSTALL BODYKITS	New	100.00	0.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
5	SPRAY PAINT FOR REAR AIRDAM,REAR BUMPER,REAR END PANEL,REAR COMPARTMENT,REAR LAMP HOUSING RH & LH,REAR FENDER RH & LH	New	3,150.00	2,100.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
9	RENEW REAR EXHAUST SYSTEM	New	300.00	0.00
10	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR Supplementary	New	225.00	225.00
11	REPLACE LH REAR FENDER, REPAIR FLOOR PANEL Supplementary	New	1,350.00	1,350.00
12	MOUNTED ONTO FLOOR BENCH TO FACILITATE REPAIR Supplementary	New	500.00	500.00
13	REMOVE & INSTALL REAR WINDSCREEN GLASS Supplementary	New	240.00	240.00
14	SUPPLY REAR WINDSCREEN SEALANT Supplementary	New	80.00	80.00
15	SPRAY PAINT FLOOR PANEL Supplementary	New	350.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,935.00</b>	<b>8,360.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**