



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDH 369Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEAD LAMP RH	NOT NECESSARY	2,138.00	-
1	FRONT FENDER SIGNAL LAMP LH	NOT NECESSARY	152.00	-
1	FRONT FENDER COWLING LH	NOT NECESSARY	368.00	-
	LESS 10% DISCOUNT		-265.80	-
			2,392.20	-
<u>SPECIAL NETT ITEMS</u>				
1	CARBON FIBER FRONT BUMPER (SN)	CRACKED	15,800.00	14,600.00
1	FRONT BUMPER RETAINER LH (SN)	NOT NECESSARY	128.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	89.00	40.00
1	HEADLAMP SUPPORT BRACKET LH (SN)	NOT NECESSARY	80.00	-
2	FRONT CARBON FIBER CARNARDS @\$480.00 (SN)	CRACKED	960.00	960.00
1	FRONT FENDER COWLING CLIPS LH (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER PAINT PROTECTION FILM (SN)	NECESSARY	480.00	480.00
1	FRONT FENDER PAINT PROTECTION FILM LH (SN)	NOT NECESSARY	280.00	-
1	JOINT SEALANT (SN)	NOT NECESSARY	120.00	-
1	CF FRONT LIP (SN)	CRACKED	1,800.00	1,800.00
			19,817.00	17,880.00
<u>LABOUR</u>				
	LABOR TO REM-RENEW OF PARTS FOR REPAIRS.		1,680.00	250.00
			1,680.00	250.00
GRAND TOTAL			23,889.20	18,130.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,500.00

Report Ref No. CS/AGI21012629/Rvf3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.