



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TAN ENG HONG
	Reg No/Reg Date	SMD6350A / 29/08/201
	Date In/Mileage	/ 52633
	Chassis No	KNAF3416MK5009840
	Engine No	G4FGJH702480
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	13/12/2021/ 13:40	BLE	261 / Edwin Caina	43931			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FR BUMPER , FR SUPPORT & BONNET								
REPAIR LHF FENDER & RHF FENDER								1400.00
E PNT98000								
RESPRAY FR BUMPER , BONNET , LHF FENDER & RHF FENDER								100.00
E PNT88000								
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								
TOP UP AC GAS								30.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								50.00
M SUNDRY								
SUPPLY FR NUMBER PLATE WITH CASING								120.00
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								
Sundries								
M	LAMP ASSY-HEAD,LH				1.00	1219.00	20.00	975.20
M	LAMP ASSY-HEAD,RH				1.00	1219.00	20.00	975.20
M	COVER-FR BUMPER				1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER				1.00	262.00	20.00	209.60
M	CAP-FRONT HOOK				1.00	9.00	20.00	7.20
M	GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE				1.00	38.00	20.00	30.40
M	LAMP ASSY-FRONT FOG,LH				1.00	303.00	20.00	242.40
M	LAMP ASSY-FRONT FOG,RH				1.00	303.00	20.00	242.40
M	MOULDING-FRONT BUMPER,LH				1.00	36.00	20.00	28.80
M	MOULDING-FRONT BUMPER,RH				1.00	36.00	20.00	28.80
M	LAMP ASSY-SIDE REPEATER,LH				1.00	143.00	20.00	114.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TAN ENG HONG
	Reg No/Reg Date	SMD6350A / 29/08/201
	Date In/Mileage	/ 52633
	Chassis No	KNAF3416MK5009840
	Engine No	G4FGJH702480
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	13/12/2021/ 13:40	BLE	261 / Edwin Caina	43931	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE REPEATER,RH		1.00	143.00	20.00	114.40
M	ABSORBER-FRONT BUMPER ENERGY		1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR		1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG		1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG		1.00	22.00	20.00	17.60
M	BEAM COMPLETE-FR BUMPER		1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE		1.00	675.00	20.00	540.00
M	ORNAMENT-KIA NO.115		1.00	32.00	20.00	25.60
M	PANEL ASSY-HOOD		1.00	1502.00	20.00	1201.60
M	HINGE ASSY-HOOD,LH		1.00	43.00	20.00	34.40
M	HINGE ASSY-HOOD,RH		1.00	43.00	20.00	34.40
M	PAD-HOOD INSULATING		1.00	156.00	20.00	124.80
M	CLIP-HOOD INSULATING PAD MTG		13.00	1.00	20.00	10.40
M	LATCH ASSY-HOOD		1.00	103.00	20.00	82.40
M	CONDENSER ASSY-COOLER		1.00	687.00	20.00	549.60
M	GUARD-AIR,LH		1.00	28.00	20.00	22.40
M	GUARD-AIR,RH		1.00	28.00	20.00	22.40
M	RADIATOR ASSY		1.00	646.00	20.00	516.80
M	BLOWER ASSY		1.00	656.00	20.00	524.80
Estimate						
SURVEYOR NAME : _____						
SURVEYOR SIGNATURE : _____						
DATE : _____						
REMARKS : _____						

Confirm & accepted by

Net 12,018.40
 7% GST on 12018.40 841.29
Total Payable 12,859.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.